

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company	Contact Merle Lewis, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Bilbrey 33 CTB 1 (closest location Bilbrey 33 Fed Com 4H)	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-41807
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter I	Section 33	Township 21S	Range 32E	Feet from the 2600'	North/South Line FSL	Feet from the 1300'	East/West Line FEL	County Lea
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	---------------

Latitude_32.4351044_ Longitude_103.6754456_ NAD83

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 95 MCF	Volume Recovered 0 MCF
Source of Release Three Phase Separator	Date and Hour of Occurrence June 5, 2018 @ 6:10 PM	Date and Hour of Discovery June 5, 2018 @ 6:10 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*


The Back Pressure Valve on the Three Phase Separator failed causing gas to vent through the Pressure Relief Valve. The wells were shut in to stop the release.

Describe Area Affected and Cleanup Action Taken.*
Approximately 95 MCF was released.

RECEIVED

By Olivia Yu at 2:35 pm, Jun 18, 2018

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature: <i>Sheila Fisher</i>			
Printed Name: Sheila Fisher			
Title: Field Admin Support		Approval Date: 6/18/2018	Expiration Date:
E-mail Address: Sheila.Fisher@dvn.com		Conditions of Approval:	
Date: 6/12/18 Phone: 575.748.1829			
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nOY1816952620

Bilbrey 33 CTB 1(closest location Bilbrey 33 Fed COM 4H)

95 MCF_6.5.18



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere

Prepared by: Sheila Fisher

Map is current as of: 12-Jun-2018



Miles

0 0.01 0.02 0.04 1:1,779

S33, T21S, R32E

95 MCF

21 S - 32 E - 33
NWSE