

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443	
Facility Name: Macho Nacho 7 State SWD #001	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No.: 30-025-42463

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	7	24S	33E	2000	North	2200	West	Lea

Latitude: 32.234001151 Longitude: -103.61263191 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 14bbls	Volume Recovered: 14bbls
Source of Release: Tank Overflow	Date and Hour of Occurrence: 2/10/2018 9:30am	Date and Hour of Discovery: 2/10/2018 9:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A third party truck driver overflowed a water tank due to human error.

Describe Area Affected and Cleanup Action Taken.*

All of the fluid remained inside of the lined containment. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

APPROVED

By CHernandez at 2:48 pm, Jun 26, 2018

Signature: <i>DeAnn Grant</i>		OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: <i>CH</i>	
Title: HSE Administrative Assistant	Approval Date: 6/26/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: agrant@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: May 14, 2018	Phone: (432) 253-4513		

* Attach Additional Sheets If Necessary

nOY1804546888

From: [Hernandez, Christina, EMNRD](#)
To: ["DeAnn Grant"; Mann, Ryan](#)
Cc: ["Sheldon Hitchcock"; "Dakota Neel"; "Rebecca Haskell"; "Robert McNeill"](#)
Subject: RE: (C-141 Final) Macho Nacho 7 State SWD #001 (30-025-42463) 2-10-2018
Date: Tuesday, June 26, 2018 3:27:00 PM
Attachments: [image001.png](#)
[image002.png](#)
[Approved \(C-141 Final\) Macho Nacho 7 State SWD #001 \(30-025-42463\) 2-10-2018.pdf](#)

Dear Ms. Grant:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **nOY1804546888** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

NMSLO like approval required.

Thanks,

Christina Hernandez
EMNRD-OCD
Environmental Specialist
1625 N. French Drive
Hobbs, NM 88240
575-393-6161 x111
Christina.Hernandez@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Yu, Olivia, EMNRD
Sent: Friday, June 22, 2018 10:26 AM
To: Hernandez, Christina, EMNRD <Christina.Hernandez@state.nm.us>
Subject: FW: (C-141 Final) Macho Nacho 7 State SWD #001 (30-025-42463) 2-10-2018

From: DeAnn Grant <agrant@concho.com>
Sent: Monday, May 14, 2018 10:06 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; rmann@slo.state.nm.us
Cc: Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; Robert McNeill <RMcNeill@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: (C-141 Final) Macho Nacho 7 State SWD #001 (30-025-42463) 2-10-2018

Ms. Yu/Mr. Mann,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.