

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|------------------|--|----------------|----------------|
| Name of Company: | COG Operating LLC | Contact: | Robert McNeill |
| Address: | 600 West Illinois Avenue, Midland TX 79701 | Telephone No. | 432-683-7443 |
| Facility Name: | MC Federal #014 Battery | Facility Type: | Tank Battery |

| | | | | | |
|----------------|---------|----------------|--|---------|--------------|
| Surface Owner: | Federal | Mineral Owner: | | API No. | 30-025-38738 |
|----------------|---------|----------------|--|---------|--------------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| B | 21 | 17S | 32E | 330 | North | 2010 | East | Lea |

Latitude 32.8264313 Longitude 103.7694473

NATURE OF RELEASE

| | | | | | |
|-----------------------------|--|---|---------------------------|-----------------------------|---------------------------|
| Type of Release: | Oil | Volume of Release: | 10bbls | Volume Recovered: | 9bbls |
| Source of Release: | Gasket on Check Valve | Date and Hour of Occurrence: | December 14, 2016 8:00 am | Date and Hour of Discovery: | December 14, 2016 8:00 am |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | Date and Hour: | | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Gasket on check valve split. The gasket was repaired.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned and the impacted gravel has been removed. Fresh gravel has been placed inside the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|--|-----------------------------------|
| Signature: <i>Rebecca Haskell</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Rebecca Haskell | Approved by Environmental Specialist: <i>[Signature]</i> | |
| Title: Senior HSE Coordinator | Approval Date: 2/28/2017 | Expiration Date: xx/xx/xxxx |
| E-mail Address: rhaskell@concho.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: January 6, 2017 Phone: 432-683-7443 | Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. | |

* Attach Additional Sheets If Necessary

1RP-4528

APPROVED

By Olivia Yu at 7:41 am, Apr 10, 2017

From: Rebecca Haskell
To: [Yu, Olivia, EMNRD](#)
Cc: [Oberding, Tomas, EMNRD](#)
Subject: FW: (C-141 Final) MC Federal #014 Tank Battery 12/14/16 (30-025-38738)
Date: Friday, April 7, 2017 1:55:36 PM
Attachments: [D1 COG McFederal #14 Tank Battery Final C-141 12-14-16 \(30-025-38738\).pdf](#)

Ms. Yu,

As per our conversation on April 4, 2017, regarding lined facilities:

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]
Sent: Tuesday, February 28, 2017 4:21 PM
To: Rebecca Haskell; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD; Jim Amos (jamos@blm.gov)
Subject: [External] RE: (C-141 Final) MC Federal #014 Tank Battery 12/14/16 (30-025-38738)

**** External email. Use caution. ****

Dear Ms. Haskell:

Please see the attachment for your records.

Please inspect the liner in question. It is OCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Rebecca Haskell [mailto:RHaskell@concho.com]
Sent: Friday, January 6, 2017 2:29 PM
To: Lynch, Kristen, EMNRD <Kristen.Lynch@state.nm.us>; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD <Tomas.Oberding@state.nm.us>; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Jim Amos (jamos@blm.gov) <jamos@blm.gov>
Subject: (C-141 Final) MC Federal #014 Tank Battery 12/14/16 (30-025-38738)

Ms. Lynch / Ms. Tucker,

Attached is a Final C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



From: Rebecca Haskell
Sent: Thursday, December 15, 2016 1:17 PM
To: 'kristen.lynch@state.nm.us'; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD (Tomas.Oberding@state.nm.us); Jim Amos (jamos@blm.gov)
Subject: (C-141 Initial) MC Federal #014 Tank Battery 12/14/16 (30-025-38738)

Ms. Lynch / Ms. Tucker,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

DEC 15 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB163555232

OPERATOR

☒ Initial Report ☐ Final Report

| | | | |
|------------------|--|----------------|----------------|
| Name of Company: | COG Operating LLC <i>229137</i> | Contact: | Robert McNeill |
| Address: | 600 West Illinois Avenue, Midland TX 79701 | Telephone No. | 432-683-7443 |
| Facility Name: | MC Federal #014 Battery | Facility Type: | Tank Battery |

| | | | | | |
|----------------|---------|----------------|--|---------|--------------|
| Surface Owner: | Federal | Mineral Owner: | | API No. | 30-025-38738 |
|----------------|---------|----------------|--|---------|--------------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| B | 21 | 17S | 32E | 330 | North | 2010 | East | Lea |

Latitude 32.8264313 Longitude 103.7694473

NATURE OF RELEASE

| | | | | | |
|-----------------------------|--|---|---------------------------|-----------------------------|---------------------------|
| Type of Release: | Oil | Volume of Release: | 10bbls | Volume Recovered: | 9bbls |
| Source of Release: | Gasket on Check Valve | Date and Hour of Occurrence: | December 14, 2016 8:00 am | Date and Hour of Discovery: | December 14, 2016 8:00 am |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | Date and Hour: | | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Gasket on check valve split. The gasket was repaired.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|--|-----------------------------|--|
| Signature: <i>Rebecca Haskell</i> | OIL CONSERVATION DIVISION | | |
| Printed Name: Rebecca Haskell | Approved by Environmental Specialist: <i>[Signature]</i> | | |
| Title: Senior HSE Coordinator | Approval Date: <i>12/20/16</i> | Expiration Date: <i>N/A</i> | |
| E-mail Address: <i>rhaskell@concho.com</i> | Conditions of Approval: <i>See attached</i> | | Attached <input checked="" type="checkbox"/> |
| Date: 12/15/16 Phone: 432-683-7443 | | | |

* Attach Additional Sheets If Necessary

LRP-4528

Operator/Responsible Party,

The OCD has received the form C-141 you provided on **12/15/2016** regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number 12P-4528 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District I office in Hobbs on or before 2/1/2017. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief

1220 South St. Francis Drive

Santa Fe, New Mexico 87505

505-476-3465

jim.griswold@state.nm.us

Patterson, Heather, EMNRD

From: Lynch, Kristen, EMNRD
Sent: Tuesday, December 20, 2016 10:18 AM
To: Patterson, Heather, EMNRD; Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD
Subject: Fw: (C-141 Initial) MC Federal #014 Tank Battery 12/14/16 (30-025-38738)
Attachments: MC Federal #014 Tank Battery Initial C-141 12-14-16 (30-025-38738).pdf

From: Rebecca Haskell <RHaskell@concho.com>
Sent: Thursday, December 15, 2016 12:16 PM
To: Lynch, Kristen, EMNRD; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD; Jim Amos (jamos@blm.gov)
Subject: (C-141 Initial) MC Federal #014 Tank Battery 12/14/16 (30-025-38738)

Ms. Lynch / Ms. Tucker,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.