

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	OGRID# [229137]	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: BEBIDAS 16 STATE SWD #001	Facility Type: Tank Battery	

Surface Owner: State	Mineral Owner:	API No. 30-025-25518
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter L	Section 16	Township 23S	Range 33E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.3029213 Longitude 103.5836792

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 33bbls	Volume Recovered: 31bbls
Source of Release: Filter Pot	Date and Hour of Occurrence: 4/20/2017 8:50 am	Date and Hour of Discovery: 4/20/2017 8:50 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Ms. Groves - SLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 4/21/2017	Time of this email
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 7:48 am, Jun 08, 2017

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole that developed in the bottom of the filter pot. Repair filter pot and return back to service.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior HSE Coordinator	Approval Date: 6/8/2017	Expiration Date: xx/xx/xxxx
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 6, 2017 Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

nOY1711439346

From: Rebecca Haskell
To: [Yu, Olivia, EMNRD](mailto:Yu.Olivia@EMNRD.org); [Amber Groves \(agroves@SLO.state.nm.us\)](mailto:agroves@SLO.state.nm.us)
Cc: [Oberding, Tomas, EMNRD](#); [Dakota Neel](#); [Rebecca Haskell](#)
Subject: (C-141 Final) Bebidas 16 State SWD #001 4/20/17 (30-025-25518)
Date: Tuesday, June 6, 2017 3:53:47 PM
Attachments: [Bebidas 16 State SWD #001 \(TB\) Notification & Initial C-141.pdf](#)
[Bebidas 16 State SWD #001 \(TB\) Final C-141 4-20-17 \(30-025-25518\).pdf](#)

Ms. Yu,

As per our conversation on April 4, 2017, regarding lined facilities:

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Robert Grubbs

Sent: Friday, April 21, 2017 10:33 AM

To: olivia.yu@state.nm.us; Oberding, Tomas, EMNRD (Tomas.Oberding@state.nm.us); 'agroves@slo.state.nm.us'

Subject: (Notification & Initial C-141) Bebidas 16 State SWD #001 4/20/17 (30-025-25518)

MS. YU / MS. GROVES,

ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.
SR. HSE COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.861.6801 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	OGRID# [229137]	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: BEBIDAS 16 STATE SWD #001	Facility Type: Tank Battery	

Surface Owner: State	Mineral Owner:	API No. 30-025-25518
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	16	23S	33E	1980'	South	660'	West	Lea

Latitude 32.3029213 Longitude 103.5836792

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 33bbls	Volume Recovered: 31bbls
Source of Release: Filter Pot	Date and Hour of Occurrence: 4/20/2016 8:50 am	Date and Hour of Discovery: 4/20/2016 8:50 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Ms. Groves - SLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 4/21/2017	Time of this email
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 10:52 am, Apr 24, 2017



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole that developed in the bottom of the filter pot. Repair filter pot and return back to service.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: 	
Title: Senior HSE Coordinator	Approval Date: 4/24/2017	Expiration Date:
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 21, 2017 Phone: 432-683-7443	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1711439346

From: [Yu, Olivia, EMNRD](#)
To: ["Robert Grubbs"; Oberding, Tomas, EMNRD; "agroves@slo.state.nm.us"](#)
Subject: RE: (Notification & Initial C-141) Bebidas 16 State SWD #001 4/20/17 (30-025-25518)
Date: Monday, April 24, 2017 11:00:00 AM
Attachments: [COG Bebidas State 002H \(TB\) Final.pdf](#)

Dear Mr. Grubbs:

Please see the attachment for your records.

Please inspect the liner in question. It is OCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Robert Grubbs [mailto:RGrubbs@concho.com]
Sent: Friday, April 21, 2017 9:33 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Oberding, Tomas, EMNRD <Tomas.Oberding@state.nm.us>; 'agroves@slo.state.nm.us' <agroves@slo.state.nm.us>
Subject: (Notification & Initial C-141) Bebidas 16 State SWD #001 4/20/17 (30-025-25518)

Ms. YU / Ms. GROVES,

ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.
SR. HSE COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.961.6801 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701