

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (OGRID #229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443	
Facility Name: Lightning 1 State SWD #001	Facility Type: Salt Water Disposal	
Surface Owner: State	Mineral Owner: State	API No. 30-025-40917

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	01	21S	33E	3,480	South	2,300	South	Lea

Latitude 32.5100899 Longitude -103.5271454 NAD83

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 300 bbl.	Volume Recovered 300 bbl.
Source of Release 3 rd Party	Date and Hour of Occurrence August 5, 2018 6:00pm	Date and Hour of Discovery August 5, 2018 6:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu – NMOCD Christina Hernandez – NMOCD Ryan Mann – SLO	
By Whom? Sheldon Hitchcock	Date and Hour August 6, 2018 12:37pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
By Olivia Yu at 10:27 am, Aug 20, 2018



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a 3rd party driver not unhooking from the load line before driving away. A second driver for the same company hooked up to load line #2 and started unloading when he noticed the water coming out and stopped.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant	Approval Date: 8/20/2018	Expiration Date:	
E-mail Address: agrant@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: August 13, 2018	Phone: (432) 253-4513	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1823237447

From: Sheldon Hitchcock
To: [Yu, Olivia, EMNRD](#); [Hernandez, Christina, EMNRD](#); [Mann, Ryan](#)
Cc: [Rebecca Haskell](#); [Dakota Neel](#); [DeAnn Grant](#); [Robert McNeill](#); [Ike Tavarez](#)
Subject: (Notification) Lightning 1 State SWD #001 (30-025-40917) 8/5/2018
Date: Monday, August 6, 2018 12:36:47 PM

Ms. Yu/Mr. Mann,

COG Operating, LLC (OGRID# 229137) is reporting a release at the Lightning 1 State SWD #001 (30-025-40917). At this time it appears that all of the fluid has remained inside of the lined containment.

Release Location:

ULSTR: F-1-T21S-R33E

Lat/Long: 32.5100899 -103.5271454

Release Volume: >25bbbls

Recovery Volume: On going

COG will have the release evaluated and will submit an initial C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

Sheldon L. Hitchcock
HSE Coordinator
COG Operating LLC
2407 Pecos Avenue | Artesia, NM 88210
Cell: 575-703-6475 | Office: 575-746-2010
slhitchcock@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG

Operating LLC or its affiliates.