

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: Chevron USA, Inc.	Contact: Alison Campestre	
Address: 6301 Deauville Blvd., Midland, TX, 79706	Telephone No.: 281-615-2381	
Facility Name: Mexico J and L Tank Battery	Facility Type: Tank Battery	
Surface Owner: State surface	Mineral Owner: State surface	API No.: Attached

LOCATION OF RELEASE

Unit Letter B	Section 5	Township 25S	Range 38E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line West	County
-------------------------	---------------------	------------------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------

Latitude 32.1631333° Longitude -103.0823667° NAD83

NATURE OF RELEASE

Type of Release: Air	Volume of Release: 128.125 MCF	Volume Recovered: 0 MCF
Source of Release: Flare	Date and Hour of Occurrence: 06/11/2018 07:00	Date and Hour of Discovery: 06/11/2018 07:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu	
By Whom? Alison Campestre	Date and Hour: 06/11/2018 at 13:36 (left voicemail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Flaring was due to a third-party gas plant shut-in. Chevron kept in close contact with Targa to ensure that flaring was stopped as soon as the plant could receive gas. 128.125 MCF was released over 123 hours.		
Describe Area Affected and Cleanup Action Taken.* N/A		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
6/26/2018 X Alison Campestre Alison Campestre Environmental Compliance Specialist Signed by: Alison Campestre Signature:	OIL CONSERVATION DIVISION Approved by Environmental Specialist: 	
Printed Name: Alison Campestre		
Title: Environmental Compliance Specialist	Approval Date:	Expiration Date:
E-mail Address: alison.campestre@chevron.com	Conditions of Approval:	
Date: 06/26/2018 Phone: 281-615-2381	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

NOY1829649023

Current Well Information

Area	ANDREWS FOT	
Sub Area	DOLLARHIDE PT	
Operator Route	4013003 - DHU ROUTE 3	
Collection Point	MEXICO J-L FAC	
WELL NAME	API 14	PRA WELL NO
MEXICO J #26	30025265230002	42857502
MEXICO J 04	30025122980001	42818801
MEXICO L 04	30025123680001	42821701
MEXICO L 27 DEV	30025353360002	44620802