

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chevron USA, Inc.	Contact: Alison Campestre	
Address: 6301 Deauville Blvd., Midland, TX, 79706	Telephone No.: 281-615-2381	
Facility Name: State BB&L Tank Battery	Facility Type: Tank Battery	
Surface Owner: State surface	Mineral Owner: State surface	API No.: Attached

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	02	25S	37E	1655	North	990	West	

Latitude 32.161282 Longitude -103.137809 NAD83

NATURE OF RELEASE

Type of Release: Air	Volume of Release: 1025 MCF	Volume Recovered: 0 MCF
Source of Release: Flare	Date and Hour of Occurrence: 06/11/2018 07:00	Date and Hour of Discovery: 06/11/2018 07:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu	
By Whom? Alison Campestre	Date and Hour: 06/11/2018 at 13:36 (left voicemail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.: N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Accepted for record


Describe Cause of Problem and Remedial Action Taken.*

Flaring due to a third-party gas plant shut-in. Chevron kept in close contact with Targa to ensure that flaring was stopped as soon as the plant could receive gas. 1025 MCF was released over 123 hours.

Describe Area Affected and Cleanup Action Taken.*
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

6/26/2018	Approved by Environmental Specialist: 	
X Alison Campestre Alison Campestre Environmental Compliance Specialist Signed by: Alison Campestre		
Printed Name. Alison Campestre		
Title: Environmental Compliance Specialist	Approval Date:	Expiration Date:
E-mail Address: alison.campestre@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/26/2018	Phone: 281-615-2381	

* Attach Additional Sheets If Necessary

NOY1829633481

Current well information

Area	ANDREWS FOT	
Sub Area	DOLLARHIDE PT	
Operator Route	4013003 - DHU ROUTE 3	
Collection Point	NM ST- BB, BZ, L	
WELL NAME	API 14	PRA WELL NO
NM BZ 10-6	30025331680102	44620602
NM BZ NCT 10-05	30025330890099	42900199
NM BZ NCT 10-07	30025339520003	42909103
STATE BB 03	30025331690099	42900899
STATE L 03	30025114170099	42806599
STATE L 04	30025114190099	42806699
STATE L 05	30025329110099	42898599
STATE L 06	30025337250099	42907199