#### Form 3160-5 (June 2015)

## Rec'd 8/5/2020 - NMOCD

**UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM63365

# SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					14101141010000		
					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well     ☐ Gas Well ☐ Other					8. Well Name and No. TANK FEDERAL 02		
Name of Operator					9. API Well No. 30-025-30112-00-S1		
3a. Address 5400 LBJ FREEWAY SUITE DALLAS, TX 75240	. (include area code 1-5200 -5201	·)	10. Field and Pool or Exploratory Area YOUNG-BONE SPRING, NORTH				
4. Location of Well (Footage, Sec., T		11. County or Parish, State		State			
Sec 1 T18S R32E SWSW 330FSL 990FWL					LEA COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	ΓΕ NATURE C	OF NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION TYPE OF ACTION							
Notice of Intent     ■     Notice of Intent     Notice of Inten	☐ Acidize	□ Dee	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	olete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon		arily Abandon		
	☐ Convert to Injection	Plug	Back	■ Water Disposal			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for f BLM BOND No. NMB001079 SURETY BOND No. RLB 001	rk will be performed or provide operations. If the operation re- condonment Notices must be fil- inal inspection.	the Bond No. or sults in a multipl	file with BLM/BL e completion or rec	A. Required sul ompletion in a r	osequent reports must be new interval, a Form 316	filed within 30 days 0-4 must be filed once	
Requesting to extend TA statu	us for this well as we eval	uate for future	Wolfcamp reco	ompletion.			
07/22/20 Gave 24 hr notice o	f MIT testing to BLM office	э.					
07/23/20 Pressured up on cs	g and CIBP to 520 psi and	d held for 30 r	min. for MIT.				
Chart attached shows pressur by Jon Staton w/BLM, Lea Co		) psi, as witne	essed	Acc	epted - NMOCD		
14. I hereby certify that the foregoing is	true and correct.  Electronic Submission # For MATADOR P nmitted to AFMSS for proce	RODUCTION	COMPANY, sent SCILLA PEREZ o	to the Hobbs on 07/27/2020	(20PP3160SE)		
Name(Printed/Typed) AVA L MC	ONROE		Title SR. EN	IGINEERING	TECHNICIAN		
Signature (Electronic S	Submission)		Date 07/27/2	2020			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
_Approved_By_JONATHON SHEPARD			TitlePETROE	LUM ENGINI	EER	Date 08/04/202	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Hobbs				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

#### Revisions to Operator-Submitted EC Data for Sundry Notice #523168

**Operator Submitted BLM Revised (AFMSS)** 

TA NOI TA NOI Sundry Type:

NMNM63365 NMNM63365 Lease:

Agreement:

MATADOR PRODUCTION COMPANY 5400 LBJ FREEWAY SUITE 1500 DALLAS, TX 75240 Ph: 972.371.5200 Operator:

MATADOR PRODUCTION COMPANY 5400 LBJ FREEWAY, STE. 1500 DALLAS, TX 75240

Ph: 214-616-4723

AVA L MONROE AVA L MONROE Admin Contact:

SR. REGULATORY ANALYST SR. ENGINEERING TECHNICIAN

E-Mail: amonroe@matadorresources.com E-Mail: amonroe@matadorresources.com

Cell: 972-371-5200 Ph: 972-371-5200 Ph: 972-371-5200 Fx: 972-371-5201 Fx: 972-371-5201

Tech Contact: AVA L MONROE AVA L MONROE

SR. REGULATORY ANALYST SR. ENGINEERING TECHNICIAN E-Mail: amonroe@matadorresources.com E-Mail: amonroe@matadorresources.com

Cell: 972-371-5200 Ph: 972-371-5200 Ph: 972-371-5200 Fx: 972-371-5201 Fx: 972-371-5201

Location:

State: County: NM UNITED STATES NM LEA

Field/Pool: YOUNG-BONE SPRING, NORTH YOUNG-BONE SPRING, NORTH

Well/Facility: TANK FEDERAL 02 TANK FEDERAL 02

Sec 1 T18S R32E Mer NMP SWSW 330FSL 990FWL Sec 1 T18S R32E SWSW 330FSL 990FWL

### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.