

# State Of New Mexico

## Energy, Minerals and Natural Resources Department

---

**Michelle Lujan Grisham**

Governor

**Sarah Cottrell Propst**


Cabinet Secretary

**Todd E. Leahy, JD, PhD**

Deputy Cabinet Secretary

**Adrienne Sandoval**

Division Director



### **"Response Required - Deadline Enclosed"**

*Field Inspection Program*

*"Preserving the Integrity of Our Environment"*

28-Dec-20

**EOG RESOURCES INC**

P.O. Box 2267

Midland, TX 79702

**LETTER OF VIOLATION - Field Inspection**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### ***INSPECTION DETAIL SECTION***

[30-025-29503] HUMMINGBIRD ADM STATE #001

OGRID: 7377

H-08-16S-37E 2086 FNL 554 FEL

<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Corrective Action Due By</b>	<b>Inspection No.</b>
12/9/2020	Routine Inspection	[EZB] Eugene Bolton	3/31/2021	iEZB2034440343

#### **Violations:**

##### **Rule**

19.15.29 Releases

##### **Comment:**

Remove prod water / hydrocarbon release at least 40 ft radius path from wellhead, has been topped with gravel, caliche, and rock, nearby scattered gravel pile.

19.15.16.18 Well and Lease Equipment

##### **Comment:**

Sharp metal conduit causing tire hazard.

##### **Violation**

Surface Leaks/Spills

Substandard Equipment and/or  
Needs Repair

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Hobbs OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

---

Oil Conservation Division \* 1625 N. French Drive \* Hobbs, NM 88240  
Phone: 575-393-6161 \* Fax: 575-393-0720 \* [www.emnrd.state.nm.us](http://www.emnrd.state.nm.us)