

State Of New Mexico

Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham

Governor

Sarah Cottrell Propst

Cabinet Secretary

Todd E. Leahy, JD, PhD

Deputy Cabinet Secretary

Adrienne Sandoval

Division Director



"Response Required - Deadline Enclosed"

Field Inspection Program

"Preserving the Integrity of Our Environment"

28-Dec-20

ARMSTRONG ENERGY CORP

P.O. Box 1973

Roswell, NM 88202

LETTER OF VIOLATION - Field Inspection

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-025-30902] MADDUX 17 C #001

OGRID: 1092

C-17-16S-37E 660 FNL 2130 FWL

Inspection Date	Type Inspection	Inspector	Corrective Action Due By	Inspection No.
12/9/2020	Routine Inspection	[EZB] Eugene Bolton	3/31/2021	iEZB2034434943

Violations:

Rule

19.15.29 Releases

Violation

Surface Leaks/Spills

Comment:

Remove production water/hydrocarbon, of over 50 ft radius from wellhead. Some areas have been covered with caliche from a pile placed near pump jack. 5 bbl threshold requires form C-141.

19.15.10.8 Safety Procedures for Drilling and Production

General
Housekeeping
Required

Comment:

Weed farm around equipment and inside TB/separator berm, unused drum inside berm, net missing from containment vat with unmarked chem container, pvc vent pipe on prod water tank.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



Eugene Bolton, Compliance Ofc.

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division * 1625 N. French Drive * Hobbs, NM 88240
Phone: 575-393-6161 * Fax: 575-393-0720 * www.emnrd.state.nm.us