1000 Rio Brazos Rd. Aztec, NM 87410         District IV         1220 S. St. Francis Dr., Santa Fe, NM         87505         SUNDRY NOTICES A         (DO NOT USE THIS FORM FOR PROPOSA         A DIFFERENT RESERVIOR. USE "APPLIC         PROPOSALS.)         1. Type of Well: Oil Well         2. Name of Operator		VISION 5. Indicate Typ 5. State Oil & 6. State Oil & 7. Lease Nam BACK TO	30-025-05973         pe of Lease         STATE       FEE         Gas Lease No.         ne or Unit Agreement Name         Bertha "J" Barber         er         1		
3. Address of Operator 303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705			10. Pool Name Eunice Monument; Grayburg/SA		
4. Well Location Unit Letter H Section 7	2310 feet from the N Township 20S Range Elevation (Show whether DR, RKB,R7 3560' GR	line and 990 fe 37E NMPM	eet from the E line County Lea		
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data         NOTICE OF INTENTION TO:         SUBSEQUENT REPORT OF:         PERFORM REMEDIAL WORK       PLUG AND ABANDON         TEMPORARILY ABANDON       CHANGE PLANS         PULL OR ALTER CASING       MULTIPLE COMPL         DOWNHOLE COMMINGLE       OWNHOLE COMMINGLE					
OTHER:       ✓       Location is ready for OCD inspection after P&A         ✓       All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.         ✓       Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.         ✓       A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
<ul> <li>The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.</li> <li>If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from the lease and well location.</li> <li>All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)</li> <li>All other environmental concrens have been addressed as per OCD rules.</li> <li>Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.</li> <li>When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one</li> </ul>					
inspection has to be made to a P&A location SIGNATURE	because it does not meet the criteria abo	ve, a penalty may be assessed.			
TYPE OR PRINT NAME Guinn Bu For State Use Only APPROVED BY: Conditions of Approval (if any):	Irks E-MAIL <u>guinn.bui</u> HohnTITLE Compli		HONE: 432-556-9143 NATE 11-29-2012		

M			~ 10
<b>I</b> DEC	Q	З.	2012