Submit 3 Copies To Appropriate District	۲.	Form C-103	
Office	State of New Mexico	October 25, 2005	
Districted a second	Energy, Minerals and Natural Resource	es WELL API NO.	
1625 N. French Dr., Hobbs, NM 8824 District II	)	30-025-05961	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISIO	N 5. Indicate Type of Lease	
Disrtict III STAV 2 1 201	<u>e</u>	STATE FEE	
1000 Rio Brazos Rd. Aztec, NM 87410	1220 South St. Francis Dr.	6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM DECEIVED )	Santa Fe, NM 87505	o. State Off & Gas Lease No.	
87505			
	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS		I North Monumont (Frayburg/SA Unit	
A DIFFERENT RESERVIOR. USE "APPLICAT PROPOSALS.)	TON FOR PERMIT (FORM C-TUT) FOR SU	8. Well Number	
1. Type of Well: Oil Well Gas Well	Other 5	283	
2. Name of Operator	,e <sup>n</sup>	9. OGRID Number	
Apache Corporation		00873	
3. Address of Operator 303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705		10. Pool Name	
4. Well Location	ste. 3000, Midiand, TX, 79705	Eunice Monument; G/SA	
Unit Letter F :	2310 feet from the N line and	2261 feet from the W line	
Section <b>6</b> To	ownship 20S Range 37I	E NMPM County Lea	
11. Ele	vation (Show whether DR, RKB,RT, GR, et	c.)	
	3575' GR	international and the second	
12. Check Appropriate Box To Indicate Na	ture of Notice, Report, or Other Data		
		SUBSEQUENT REPORT OF:	
E-restand	ND ABANDON LI REMEDIAL WORK	IG OPNS.	
OTHER:	Locatio	n is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
<ul> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> <li>A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the</li> </ul>			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
PERMANENTET STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from the lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
All other environmental concrens have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from			
non-retrieved flow lines and pipelines.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one			
inspection has to be made to a P&A location be	ecause it does not meet the criteria above, a pen	alty may be assessed.	
SIGNATURE <u>Lon Lelle</u>	TITLE P&A Tech	hnician DATE <u>11/19/12</u>	
TYPE OR PRINT NAME	E-MAIL <u>leon.sellers@ap</u>	achecorp.com_PHONE:432-208-0349	
For State Use Only			
APPROVED BY: March (th	itala TITLE Compliance	Officer DATE 01-15-2013	
Conditions of Approval (if any):			

Ch	m
$\mathcal{N}$	M