Submit One Copy To Appropriate District State of New Mexico	Form C-103
Submit One Copy To Appropriate District State of New Mexico Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II	Revised November 3, 2011 WELL API NO.
District III 1000 Rio Brazos Rd. Aztec. NM 87410 District III 1000 Rio Brazos Rd. Aztec. NM 87410 1000 Rio Brazos Rd. Aztec. NM 87410	30-025-06206
JAN 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE x FEE
District IV is Indee, INFO Proceeding Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT
1. Type of Well: Oil Well Gas Well x Other Injection	8. Well Number #174
2. Name of Operator XTO ENERGY, INC. ATTN: Stephanie Rabadue	9. OGRID Number 005380
3. Address of Operator 200 N. LORAINE, SUITE 800, MIDLAND, TEXAS 79701	10. Pool name or Wildcat Eunice Monument; Grayburg/San Andres
4. Well Location	
Unit Letter m : 330 feet from the south line and 330 feet from the west line Section 32 Township 20S Range 37E NMPM County LEA	
Section 32 Township 20S Range 37E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,540' GR 3,540' GR 3,540' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A x	
OTHER: Image: Content of the conten	ady for OCD inspection after P&A
 x Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. x A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
x The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
x Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
x If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from	
lease and well location. x All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 x All other environmental concerns have been addressed as per OCD rules. x Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
x If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE John latin TITLE Lease Operator	DATE01/14/13
TYPE OR PRINTNAME John Robinson E-MAIL: john_robinson@xtoenergy.com PHONE: _575-441-5199 For State Use Only A _	
TYPE OR PRINTNAME John Robinson E-MAIL: john_robinson@xtoenergy.com PHONE: _575-441-5199 For State Use Only APPROVED BY: DATE 01/22/2013	
	•

8