Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District 1 Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88216BBS OCOIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	30-025-39945 <b>/</b> 5. Indicate Type of Lease
1220 South St. Flancis Dr.	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NMAN 2 2 2013 Santa Fe, NM 87505	VO-7641
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSATE TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	211.4.0.4.11.5
PROPOSALS.)	NLA State Unit  8. Well Number 1Y
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator  OGX Resources LLG - Roca Production Inc	9. OGRID Number 217955 7
3. Address of Operator	10. Pool name or Wildcat
P. O. Box 2064 Midland, Texas 79702	Flying M Abo South
4. Well Location	
Unit Letter M : 480 feet from the South line and	530feet from theWestline
Section 18 Township 9S Range 33E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
4404'	1000 1600 1600 1600 1600 1600 1600 1600
12. Check Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
	•
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	<del>-</del>
TEMPORARILY ABANDON	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT	JOB []
DOWNHOLE COMMININGLE	, · ·
OTHER: OTHER:	·
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	give pertinent dates, including estimated date
proposed completion or recompletion.	ipietions. Attach wendore diagram of
L. oberes .	
Please be advised that the dry hole marker has been marked with OGX as operator when the well was plugged. The hole where the SW anchor was located is not noticeable as the landowner has plowed up the location.	
anchor was rocated is not noticeable as the landowner has proved up the rocation.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
	Section 1997
SIGNATURE TITLE Engineer	DATE 1/17/13 ·
$\mathcal{Q}$	
Type or print nameSteve Douglas E-mail address: steve@ogxresou  For State Use Only	rces.comPHONE: 432/685-1287
END DEANDY MILL	1/
APPROVED BY: TIME COLD (NZ	DATE 1/23/2013
Conditions of Approval (if any):	/ /