Submit 1 Copy To Appropriate District	State of New M	exico	Form (	
Office <u>District 1</u> – (575) 393-6161 Energy, Minerals and Natural Resources		Revised August	1, 2011	
1625 N. French Dr., Hobbs, NM 88240  District II – (575) 748-1283  OH. CONIGED VA TION DIVISION		WELL API NO. 30-025-26309		
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III - (505) 334-6178 JAN 25 201220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE		
<u>District IV</u> = (505) 476-3460 Santa Fe, NW 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505 RECEIVED		VB-1819	1	
SUNDRY NOTICES AND REPORTS ON WELLS		S	7. Lease Name or Unit Agreement N	lame
(DO NOT USE THIS FORM FOR PROPOSAL			Trucker BRK State	
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	HON FOR PERIMIT (FORM C-101) F	OK SUCH	8. Well Number	
	as Well Other		1H /	
2. Name of Operator			9. OGRID Number 025575	
Yates Petroleum Corporation  3. Address of Operator			10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210			Bell Lake; Bone Spring	
4. Well Location				
Unit Letter L :19	80 feet from the Sout	h line and 6	feet from the West	line
Unit Letter I 19	86 feet from the Sout	h line and 3	feet from the East	line
Section 2	Township 24S Ra	ange 33E	NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3615'GR				
10 61 1 4	'	T. CNT. T	0.1 5.4	
12. Check Ap	propriate Box to Indicate N	Nature of Notice, I	Report or Other Data	
NOTICE OF INT	ENTION TO:	SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK			G □	
TEMPORARILY ABANDON			LING OPNS.□ P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗆	
DOWNHOLE COMMINGLE				
OTHER:	П	OTHER: Re-entry	r procedures and production casing	$\boxtimes$
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recon	pletion.			
2/19/12- 2/28/12 - Began re-entry proc				
brine. Tested casing from surface to 8960' to 500 psi, held good. Drilled cement down to 9500'. Circulated hole clean. Pressure tested casing from surface to 9500' to 650 psi for 15 min, held good. ND BOP.				
10/14/12 – NU BOP.				
10/16/12 – TIH with tubing to a depth of 11,431' and tagged. Circulated hole clean. TOOH with tubing and bit.				
10/18/12 – ND BOP.				
11/27/12 - NU BOP. Tested casing to 1200 psi for 30 min, good. Set a CIBP at 10,630'. NOTE: Notified E.L. Gonzales NMOCD-				
Hobbs of operations via voicemail. 11/28/12 – Tagged CIBP at 10,627'. C	Circulated casing			
11/29/12 – Picked up starter mill, bit su		BHO assembly. TIH v	with whipstock to 10,609'. Broke circ	ulation
and made 15" starter cut. Circulated be	ottoms up.	•	•	
			CONTINUED ON NEVT DA	CE.
		·	CONTINUED ON NEXT PA	GE:
Spud Date: 2/19/12 Re-ent	ry Rig Release D	oate:	2/18/12	
	1			
I hereby certify that the information ab	ove is true and complete to the b	pest of my knowledge	and belief.	
I hereby certify that the information ab	ove is true and complete to the b	pest of my knowledge	and belief.	
11.				
I hereby certify that the information ab		pest of my knowledge gulatory Reporting Su		
SIGNATURE Type or print name Tina Huerta	TITLE Reg		pervisor DATE January 24, 2013	•
SIGNATURE Charles	TITLE Res	gulatory Reporting Su	pervisor DATE <u>January 24, 2013</u>	8
SIGNATURE Tina Huerta  For State Use Only	TITLE Reg	gulatory Reporting Su	pervisor DATE <u>January 24, 2013</u> PHONE: <u>575-748-416</u>	8
SIGNATURE Type or print name Tina Huerta	TITLE Res	gulatory Reporting Su	pervisor DATE <u>January 24, 2013</u> Leom PHONE: <u>575-748-416</u>	8

Yates Petroleum Corporation Trucker BRK State #1H Lea County, New Mexico Page 2

## Form C-103 continued:

11/30/12 – Finished TIH with mill assembly. Milled ramp and attempted to drill rathole from 10,604'-10,614'. Drill rate stopped once on formation. Circulated bottoms up. Changed out window mill. TIH to 10,596'. Cut 108' drilling line. Washed to 10,613'. Drilled rate hole to 10,616'.

12/1/12 – Drilled rathole with window mill. Circulated bottoms up. TOOH with mill assembly. Laid down and load out window and watermelon mill. TIH to 10,615'. Orient gyro through window. Washed to bottom from 10,615'-10,618'. Continued to drill directionally.

12/15/12 - Reached TD 6-1/8" hole to 15,075' at 9:00 AM.

12/16/12 – Set 4-1/2" 13.5# P-110 buttress casing at 15,060'. Packer stage tool at 10,479'. Float collar at 14,970'. Cemented with 350 sx PVL + 0.6% PF-13 + 30% PF-151 + 0.2% PF-153 + 5% PF-174 + 0.25#/sx PF-46 + 7% PF-606 + 0.2% PF-800 (yld 1.87, wt 13). Bumped to 3398 psi, hold ok. Dropped bomb. Inflate packer and opened tool to 1980 psi. Broke circulation. Circulated only chemical wash off of stage tool. Dropped closing plug and displaced with treater water. ND BOP.

Regulatory Reporting Supervisor

January 24, 2013