Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY Do not use the abandoned we	000	NMLC058396 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	7. If Unit or CA/Ag 8920003410	7. If Unit or CA/Agreement, Name and/or No. 8920003410			
Type of Well	8. Well Name and N				
☑ Oil Well ☐ Gas Well ☐ Oth	ner Contact: RHON	VED MCA UNIT 468			
Name of Operator CONOCOPHILLIPS COMPAN	i	30-025-39408-00-X1			
3a. Address 3300 N "A" ST BLDG 6 MIDLAND, TX 79705	l Ph:	hone No. (include area code) 432-688-9171 132-688-6019	10. Field and Pool, MALJAMAR	10. Field and Pool, or Exploratory MALJAMAR, GR, SA	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Paris	h, and State	
Sec 27 T17S R32E SENE 138 32.808988 N Lat, 103.748013	LEA COUNTY	LEA COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO IND	ICATE NATURE OF N	OTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☑ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
	Alter Casing ∴	☐ Fracture Treat	□ Reclamation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
	□ Convert to Injection	☐ Plug Back	■ Water Disposal		
following completion of the involved testing has been completed. Final Al determined that the site is ready for form that the site is ready for the site is ready for the site is the site is ready for the site is the site is ready for for for the site is ready for for the site is ready for for for for the site is ready for	pectfully request a sundry for vary casing designs, production certletion of this well while monitoring reason the cement was lappelemented in the frac'ing operations by all agencies have been peration.	a multiple completion or recorafter all requirements, including riance to the submitted Ament had to be circulated to the annulus pressure ed above the surface case on of this well after reques obtained. We will monit	APD drill plan. It to surface. during the sing shoe. st has or the annulus	1160-4 shall be filed once	
Cor	Electronic Submission #200659	IPS COMPÅNY, sent to th by KURT SIMMONS on 0:	ne Hobbs \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	MRL3	
		CIAIT I	LEGERITORI TEORINOMI	•	
Signature (Electronic	Submission)	Date 03/05/20	13		
	THIS SPACE FOR FE	DERAL OR STATE (OFFICE USE		
Approved By EDWARD FERNAN Conditions of approval, if any, are attache ertify that the applicant holds legal or equition would entitle the applicant to conditions.		······································	Date, 03/06/2013		
21 1011000 1 1001 1221 10	110 0 0 1 1212 1 1				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Sundry Request for Variance ConocoPhillips Company Maljamar; Grayburg-San Andres MCA Unit 468

Lea County, New Mexico

Request:

ConocoPhillips Company respectfully requests a sundry for variance to the submitted APD drill plan. Per requirement, on two string casing designs, production cement had to be circulated to surface. The intention is to allow completion of this well while monitoring the annulus pressure during the Frac without remediation for the reason that cement was lapped above the surface casing shoe.

Summary:

On Wednesday, February 26th, 2013, we cemented our 5-1/2" 17# J-55 LTC production casing on this well. We had full returns during the cement job, but we did not get cement returns to surface.

We believe that the reason we did not get cement returns to surface is because we did not pump sufficient excess cement. We should have been more conservative in using more excess in order to bring more cement to surface. We did, however, observe that we had full returns during the cement job and that we got back approximately 20 bbls of the 30 bbls of the fresh water spacer that we pumped ahead of the cement. We also observed that our lift pressure was 903 psi immediately prior to bumping the plug. Based on the volumetric calculations, we estimated the top of cement to be at approximately 300 ft MD and lapped approximately 600 ft MD above the surface casing shoe. The surface casing shoe is at 916 ft MD.

Monday morning, March 4th, 2013, we performed a CBL logging run per BLM requirements. The CBL log could conclusively indicate the top of cement to be approximately at 520 ft MD shown from the reduction in amplitude. The VDL also indicates significantly higher activities (wiggly characterizations on the VDL track) begin roughly at 560 ft MD. Therefore, based on these interpretations, we propose no remediation is necessary and request an approval to proceed with completing the well.

Per our discussion with the BLM Engineer, Edward Fernandez, the interpretation of the CBL was adequate which was supplied to BLM and should be in their file records.

Anticipated starting date and duration of operations:

This proposal will only be implemented in the fracting operation of this well after request has been approved and authorizations by all agencies have been obtained. We will monitor the annulus pressure during the fracting operation.

Contact Information:

Sundry Request proposed 5 March 2013 by: James Chen Drilling Engineer, ConocoPhillips Company Phone (832) 486-2184 Cell (832) 768-1647