

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

APR 15 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corporation	API Number 30-025-05721
Property Name NMGSAU	Well No. H066

1. Surface Location

UL - Lot F	Section 29	Township 19S	Range 37 E	Feet from 1980	N/S Line N	Feet from 1980	E/W Line W	County Lea
---------------	---------------	-----------------	---------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING (inj)	DATE
-------------	---------	--------------------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA



If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm Csg	(D)Prod Csg	(E)Tubing
Pressure	0		0	320	1090
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: (D) Bled oil to a truck for 20 seconds to 0

Signature: 	ELG/OCD 4-15-2013
Printed name: Jim Ellison	OIL CONSERVATION DIVISION
Title: Instrument Technician	Entered into RBDMS
E-mail Address: JD.Ellison@apachecorp.com	Re-test
Date: 3-8-13	
Phone: 575-441-7734	
Witness: 	

APR 22 2013