

Submit 1 Copy To Appropriate District  
Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

HOBBS OCD

OIL CONSERVATION DIVISION

APR 22 2013 220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

WELL API NO. 30-025-40119
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Dayton Hardy (306597)
8. Well Number 008
9. OGRID Number 873
10. Pool name or Wildcat 6660 / 60240 / 19190 / 62700
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3498' GL

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Apache Corporation

3. Address of Operator  
303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705

4. Well Location  
Unit Letter J : 2310 feet from the South line and 2160 feet from the East line  
Section 20 Township 21S Range 37E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: LOCATE/REPAIR CASING LEAK ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache performed the following:

3/19/2013 MIRUSU POOH w/pump; tbg stuck - pump 500 gal HCL down backside. 3/20/2013 POOH w/tbg, after jarring for 2 hrs.  
3/21/2013 RIH w/scrapper; work thru tight spot @ 4300' to 4306'. Tag fill @ 7096' (109' fill).  
3/22/2013 RIH w/RBP & packer. Set RBP @ 5025'; pkr @ 4286'. Located leak 4286'-4319'. POOH w/pkr.  
3/25/2013 RIH & set retainer @ 4220'. Pump 400 sx class C cmt; sting out retainer. POOH w/tbg.  
3/26/2013 DO retainer & cement and fell out @ 4320'. 3/27/2013 Pump balance plug.  
3/28/2013 DO cement to 4200'. 3/29/2013 DO cement to 4320' & fall out. 4/01/2013 Pump balance cement plug.  
4/02/2013 DO cement to 3962'; too soft. 4/03/2013 Finish DO cmt; wash sand off RBP; POOH w/DC's & bit.  
4/04/2013 RIH w/Ret head to 5025'. Retrieve RBP; RIH w/bit, DC's & tbg. Tag fill @ 7032'; CO fill 7186'. Circ clean. POOH w/2-7/8" work string.  
4/05/2013 RIH w/prod tbg (2-7/8"); SN @ 7101'. Good pump action.  
4/09/2013 MIRU Lower SN to 7132'; POP.  
4/10/2013 POOH w/rods & pump; RIH w/new pump. RTP

Spud Date: 5/20/2011

Rig Release Date: 6/1/2011

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Reesa Holland Fisher TITLE Sr. Staff Reg Tech DATE 4/16/2013

Type or print name Reesa Holland Fisher E-mail address: Reesa.Holland@apachecorp.com PHONE: 432/818-1062

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE APR 22 2013  
Conditions of Approval (if any):

APR 22 2013