HOBBS OCD

Submit One Copy To Appropriate District 2 4 2013 State of New Mexico Office APR 2 4 2013 Energy, Minerals and Natural Resources	Form C-103 Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-03198
District II 811 S. First St., Artesia, NM 88210 RECEIVEDOIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 874101220 South St. Francis Dr. Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State on te Gas Bease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Northeast Pearl Queen Unit
1. Type of Well: Oil Well Gas Well X Other Dijection Well	8. Well Number 014
2. Name of Operator Quantum Resources Management, LLC	9. OGRID Number 243874
 Address of Operator 1401 McKinney Street; Ste. #2400, Houston, TX 77010 	10. Pool name or Wildcat Pearl; Queen
4. Well Location Unit Letter G : 1980 feet from the N line and 2310 feet from the E line Section 23 Township 195 Range 35E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3787' RKB, 3774.3' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D	ata
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB CASING/CEMENT JOB	
OTHER: OTHER: D V Location is ready for OCD inspection after P&A	
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 	
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> <u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> <u>PERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u>	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. Image: All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.) Image: Market and Concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Culleta A, alale TITLE Sr. Regulatory Ana	DATE 04/22/13
TYPE OR PRINT NAME Celeste G. Dale E-MAIL: cdale@gracq.cd For State Use Only Image: Color of the state of	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
APPROVED BY: Mark Whitele TITLE Compliance	Afficer DATE 04-25-2013
APPROVED BY: Mah Whiteham TITLE Compliance Afficer DATE 04-25-2013 INJ LINE ON E. side rune to INJ Well I location south.	