

APR 29 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-32243
Property Name North Vacuum ABO North Unit	Well No. #002

7. Surface Location

UL - Lot K	Section I	Township 17S	Range 34E	Feet from 1980	N/S Line South	Feet From 1980	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING A	DATE 04-17-2013
------------------	---------	----------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure		N/A	0	55	55
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Cement was circulated to surface during original completion on surface casing.

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: <i>Trish Mealand</i>	OIL CONSERVATION DIVISION	
Printed name: Trish Mealand	Entered into RBDMS	
Title: Production Analyst	Re-test	
E-mail Address: pmcaland@limerockresources.com		
Date: 04-23-2013	Phone: 575-623-8424	
Witness:		

MAY 06 2013