

HOBBS OCD

APR 29 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-32721
Property Name North Vacuum ABO North Unit	Well No. #073

7. Surface Location

UL - Lot G	Section 1	Township 17S	Range 34E	Feet from 1980	N/S Line North	Feet From 1980	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING A	DATE 04-17-2013
------------------	---------	----------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure		N/A	0	50	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Cement was circulated to surface during original completion on surface casing.

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: 	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: pmealand@limerockresources.com	
Date: 04-23-2013	Phone: 575-623-8424
	Witness:

MAY 06 2013