Submit One Copy To Appropriate District Office State of New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240 PR 1 9 Energy, Minerals and Natural Resources	Revised November 3, 2011 WELL API NO.
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30 025 39404 5. Indicate Type of Lease
District IVI 1000 Rio Brazos Rd., Aztec, NM 87410 RECEIVED 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	VB-1128
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Moore Cowbell 27 State
PROPOSALS.) 1. Type of Well: Gas Well Other	8. Well Number 1H
2. Name of Operator	9. OGRID Number
Caza Operating, LLC	249099 10. Pool name or Wildcat
3. Address of Operator 200 N. Loraine, Suite 1550, Midland, Texas 79701	Caprock Wolfcamp, East
4. Well Location	Caproek Trendamp, Eddt
Unit Letter P: 660 feet from the South line and 990 feet from the East line	
Section 27 Township 12 S Range 32 E NMPM County L	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 4335 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D	Pata
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS P AND A CASING/CEMENT JOB CASING/CE	
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR """UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
FERMANENTLY STAMPED ON THE WARRER S SURFACE.	
 ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) ☒ All other environmental concerns have been addressed as per OCD rules. ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. ☒ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. 	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE TITLE Operations Manager DATE 4-16-2013	
TYPE OR PRINT NAME Richard L. Wright E-MAIL: rwright@cazape For State Use-Only APPROVED BY: TITLE Complian	tro.com PHONE: 432 682 7424 CO Office DATE 5/17/2013 MAY 20 2013



HOBBS OCD

MAY 1 6 2013

RECEIVED

April 9, 2013

Good Cattle Company P. O. Box 36 Elida, New Mexico 88116

hanged to H.

27 State 1 H.

23 STATE DETLED.

WAS NEVER DETLED.

Re:

Surface Release 27 Caza-Çow Bell 23 State 1H Section 23, T12S-R32E, NMPM

Lea County, New Mexico

Gentlemen:

Caza Petroleum, Inc., through its subsidiary, Caza Operating, L.L.C. has drilled, produced and permanently abandoned its Cow Bell 23 State No. 1H well. Caza has removed its equipment and restored the surface of the well site. 27

For consideration of Five Thousand Dollars (\$5,000.00), the receipt and sufficiency of which are hereby acknowledged, you hereby agree that Caza may leave all of the imported caliche in place on the well site, as is and where is. You also acknowledge and agree that the drill site has otherwise been restored and release Caza from any further damages in connection with its operations on the captioned well.

If you are in agreement with the foregoing, please sign and return this letter to me. Thank you.

Very truly yours, Caza Petroleum, Inc.

John E. Brown, CPL Land Manager

Agreed to and Accepted this / day of April, 2013.

Good Cattle Company

Printed Name: CHARLES



NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

SUSANA MARTINEZ

Governor

Jami Bailey Director Oil Conservation Division

David Martin

Cabinet Secretary-Designate Brett F. Woods, Ph.D. Deputy Cabinet Secretary

Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

30-Apr-13

CAZA OPERATING, LLC 200 N LORAINE STE 1550 MIDLAND TX 79701

HOB3S OCD

MAY 1 6 2013

RECEIVED

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

MOORE COWBELL 27 STATE No.001H

P-27-12S-32E

30-025-39404-00-00

Inspection Date

Type Inspection

*Significant Violation? Non-Compliance? Corrective

Inspection No.

04/26/2013 Plugged Well Surface Restor Maxey Brown

Yes

No

Action Due By: 7/30/2013

iMGB1311648391

Comments on Inspection:

DO NOT RELEASE. RULE 19.15.25.10. NEED TO REMOVE PROPANE TANK, FENCE POST AND WIRE FROM LOCATION. ALSO LOCATION HAS NOT BEEN LEVELLED, BRING STOCKPILED TOP SOIL BACK ONTO LOCATION, SMOOTH OUT PILES OF CALACHI. MARKER IS OK. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.

Mr Brown, The propane tanks will be removed as soon as possible. They were released 3 mos ago. The Fencing material is owned by the surface owner. Mr Good has agreed to let us leave the Caliche in place. He also agreed that leveling was not necessary subject to his inspection which has already occurred. Subject to the propane tank being remove please consider releasing Caza from further liability. Thanks.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Waley Brown

COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.