

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

HOBBS OCD

FEB 21 2013

RECEIVED

WELL API NO. 30-025-28149
5. Indicate Type of Lease Federal <input checked="" type="checkbox"/> STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-94190
7. Lease Name or Unit Agreement Name Querecho Plains Queen Asso Sand Unit
8. Well Number QPQASU #13
9. OGRID Number 14744
10. Pool name or Wildcat Querecho Plains Queens Associated
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3749' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐ Injection Well ☒

2. Name of Operator
Mewbourne Oil Company

3. Address of Operator
PO Box 5270, Hobbs, NM 88240

4. Well Location

Unit Letter N : 330' feet from the South line and 2310' feet from the West line
Section 22 Township 18S Range 32E NMPM LEA County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Integrity Test ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

An integrity test and braden head test were performed on the QPQASU #13, OK. This well is included in the Mewbourne Oil Company Querecho Plains Waterflood. This test was performed on Feb. 12, 2013. Donna Mull w/OCD was notified but did not witness. The chart for this test is attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Antonio Martinez TITLE Engineer DATE 2-19-2013

Type or print name Antonio Martinez E-mail address: amartinez@mewbourne.com PHONE: (575) 393-5905
For State Use Only

APPROVED BY: [Signature] TITLE DIST. MGR DATE 5-14-2013

Conditions of Approval (if any):

MAY 21 2013

PRINTED IN U.S.A. 6 PM

Newbome Oil Company
QP QASU #13
N-22-185-32 E
30-025-28149

DATE 2/12/2013
BR 2221

Lot
1000# / 6 min
Calib 8/22/2012

h