

MAY 14 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name John H. Hendrix Corporation	API Number 3002522709
Property Name Sun Dangle	Well No. 3

7. Surface Location

UL - Lot O	Section 13	Township 22S	Range 37E	Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status Active	SHUT-IN	PRODUCING P	DATE 04/17/13
-----------------------	---------	----------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	59			16	14
Flow Characteristics					
Puff	[Y] N	Y / N	Y / N	Y / N	
Steady Flow	Y / [N]	Y / N	Y / N	Y / N	
Surges	Y / [N]	Y / N	Y / N	Y / N	
Down to nothing	[Y] N	Y / N	Y / N	Y / N	
Gas or Oil	Y / [N]	Y / N	Y / N	Y / N	
Water	[Y] N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR XX	FRESH	SALTY	SULFUR	BLACK
----------	-------	-------	--------	-------

Remarks:

59# - with small spray of water - down to nothing in 10 seconds - (less than 1 cup)

Signature: Carolyn Doran Haynes	OIL CONSERVATION DIVISION
Printed name: Carolyn Doran Haynes	Entered into RBDMS
Title: Engineer	Re-test
E-mail Address: cdoranhaynes@jhnc.org	
Date: 4/17/13	Phone: 432-684-6631
Tested by Allon Dobbs	Witness:

MAY 22 2013