
| NODEO COE  |   | Amendea   |        |
|--|---|---|--------|
| Submit   Copy To Appropriate District  State of New Mexico   |   | Form C-10   | )3     |
| Office District 1 – (575) 393-6161 Energy, Minerals and Natural Resources  |   | Revised August 1/20   | 11.    |
| 1625 N; French Dr., Hobbs, NM 88240 1 5 2013  District II - (575) 748-1283   |   | WELL API NO. 30-025-08569   |        |
| 811 S, First St., Artesia, NM 88210 OIL CONSERVATION DIVISION  |   | 5. Indicate Type of Lease   | بستنسد |
| District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 874 RECEIVED 1220 South St. Francis Dr. 1220 South St. Francis Dr. 1220 South St. Francis Dr.   |   | STATE X FEE   |        |
| District IV - (505) 476-3460 1220 S, St. Francis Dr., Santa Fe, NM  Santa Fe, NM  S7505  |   | 6. State Oil & Gas Lease No.<br>E-8322                              |        |
| 87505  |   | · · · · · · · · · · · · · · · · · · ·                               |        |
| SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A   |   | 7. Lease Name or Unit Agreement Name                                | - 1    |
| DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  |   | Jalmat Field Yates Sand Unit  | . 1    |
| PROPOSALS.)  1. Type of Well: Oil Well Gas Well X Other Injection  |   | 8. Well Number 102  |        |
| 2. Name of Operator  |   | 9. OGRID Number 243874  |        |
| Quantum Resources Management, LLC  |   | 10. Pool name or Wildcat  |        |
| 3. Address of Operator<br>1401 McKinney St., Suite #2400; Houston, TX 77010  |   | Artesia; Queen-Grayburg-San Andres                                  |        |
| 4. Well Location   |   |   |        |
| Unit Letter P : 330 feet from the South  | line and                                | 330 feet from the East / line                                       | . ],   |
|  | inge 35E                                | NMPM Lea County   | 1      |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.)   |   |   |        |
| 3612' GR   |   |   |        |
| 12. Check Appropriate Box to Indicate N  | ature of Notice                         | Report or Other Data  |        |
| •••  |   |   |        |
|  |   | SEQUENT REPORT OF:  | 7      |
| PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE OF  |   | K ☐ ALTERING CASING ☐<br>ILLING OPNS.☐ P AND A ☐                    | ]<br>] |
| PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN   |   | <del></del>   |        |
| DOWNHOLE COMMINGLE   |   | _   |        |
| OTHER:   | OTHER MACE                              | cated incoming that   | ก      |
| OTHER:  13. Describe proposed or completed operations. (Clearly state all proposed or completed operations)  | pertinent details, and                  | anical Integrity Test d give pertinent dates, including estimated d | ate    |
| of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of   |   |   |        |
| proposed completion or recompletion.   |   |   |        |
| Injection well re-activated. Mechanical integrity test dated 0   | 5/30/13, (555) psi                      | i, chart attached.  |        |
| Test witnessed by Mark Whitacker, NMOCD Hobbs office.  |   |   |        |
|  |   |   |        |
|  |   |   |        |
|  |   |   |        |
|  |   |   |        |
|  |   |   |        |
|  |   |   |        |
|  |   |   |        |
|  | j <del> </del>                          | <del></del>   |        |
| Spud Date: Rig Release Da  | te:                                     |   |        |
|  | t                                       |   |        |
| [heady, cost: 6, th, 44h, i. 6, time about in the second seco | at af man brandada                      | and holiaf  |        |
| I hereby certify that the information above is true and complete to the be   | st of my knowledge                      | and belief.   |        |
|  |   |   |        |
| SIGNATURE CULLATE A WALL TITLE Sr. Re  | gulatory Analyst                        | DATE 06/10/13   | ·      |
| Type or print name Celeste G. Dale E-mail address:   | cdale@gracq.co                          | om PHONE: 432-683-1500  |        |
| For State Use Only   | , i i i i i i i i i i i i i i i i i i i |   | بشت    |
| APPROVED BY Makey & Brown Title Compliance Office DATE 7/16/2013   |   |   |        |
| Conditions of Approval (if any)  | - Herrice                               | <u> </u>  |        |
| I 4  |   | <del></del>   |        |



## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

John H. Bemis Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director Oil Conservation Division



## Letter of Violation IMMEDIATE DIRECTIVE

RECEIVED

March 28, 2013

APR 0 3 2003

Quantum Resources Management, LLC. 1401 McKinney Street Ste. 2400 Houston, TX 77010

Attn: Regulatory Department

E: CONE JALMAT YATES (CJYPU) #111, S13-T22S-R35E UNIT P

JALMAT YATES SAND UNIT (JYSU) # 102, S3-T22S-R35E UNIT P

## Dear Operator:

After conducting the Annual UIC Testing, it has come to our attention that the above referenced wells presently are out of compliance with OCD Rules and Regulations.

According to records, the OCD District I office has not yet received a Subsequent Report C103 stating a workover attempt, performed in February of 2012 on the CJYPU #111. According to field information, clean out work and tubing construction was/has been modified to well #111and the packer has been set above the allowed depth.

In order to bring CJYPU #111 into compliance with OCD Injection Rules 19.15.26.10; 19.15.26.11 and the EPA UIC requirements, please do the following:

- > Submit a Subsequent Report C103 stating in detail work performed February 2012.
- A packer setting depth must be submitted and approval from Santa Fe must be obtained, if the packer is set more than 100' above the top perforation.
- ▶ Please note that wells out of compliance with NMOCD Rule 19.15.5.9 will be listed on the Inactive Well List.

March 28, 2013 Page 2

In reference to JYSU #102 the Temporarily Abandonment status has expired. According to OCD Rule 19.15.25.13; 19.15.25.14 Operator must do the following:

- > Submit NOI C103 and wellbore schematic requesting an extension of TA Status for 1 year only.
- ➤ After approval of NOI, perform a mechanical integrity test on JYSU #102. (500#/30 mins)
- > Submit Subsequent Report C103 with detailed information and pressure test chart for approval.

If you have any questions, please contact EL Gonzales, at 575-393-6161 x102.

Sincerely,

EL Gonzales

OCD District I Supervisor