Submit One Copy To Appropriate Districts OCD State of New Mexico	Form C-103
Energy Minerals and Netural Passuroes	Revised November 3, 2011 WELL API NO.
District 1 1625 N. French Dr., Hobbs, NM/88240 District II 811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis Dr.	30-025-09940
811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 874-10 District IV 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State on the Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Alice Paddock
PROPOSALS.) 1. Type of Well: Gas Well Other:	8. Well Number: 4
2. Name of Operator Chevron USA, Inc.	9. OGRID Number 4323
3. Address of Operator	10. Pool name or Wildcat
15 Smith Road Midland, TX 79705	Blinebry Oil & Gas (Oil)
4. Well Location	
Unit Letter G: 1980 feet from the North line and 1980 feet from the East line	
Section: 1 Township: 22-S Range 37-E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, ea	
3367' DF	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other	Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WO TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE D	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to s	chedule an inspection.
$\mathcal{O}_{\mathcal{O}}}}}}}}}}$	
	wst. Rep DATE 8-4-13
TYPE OR PRINT NAME /3:11 BECK E-MAIL: WBDS@Cheurou.com PHONE: 575-390-1412 For State Use Only N	
APPROVED BY: Manh Withdam TITLE Comptione Officer DATE 08-20-2013 AUG 2.2 2013	
	AUG 2.2 2013