Submit One Copy To Appropriate District		•	T	C 102
Office	State of New Me			Form C-103 vember 3, 2011
Energy, Minerals and Natural Resources 625 N. French Dr., Hobbs, NM 88240		WELL API NO.		
District II OIL CONSERVATION DIVISION		DIVISION	30-25-25536	
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM			310684	
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			QUAIL QUEEN UNIT	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number # 00/		
2. Name of Operator			9. OGRID Number	
CHEVRON USA INC.			10. Pool name or Wildcat	
3. Address of Operator				
4. Well Location			QUEEN/PA	
Unit Letter O: feet from the 660 \$ line and 698 deet from the E line				
Section _// Township /95 Range 34E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3964				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK DUID AD ABANDON I REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLOG AND ABANDON C NAMEDIAL WORK CASING CASING C				
PULL OR ALTER CASING				hinned.
OTHER: Determined in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
ODED ATOD NAME A DAGE NAME WOLL MUMORE ADI MUMPER OUADTED OUADTED I OCATION OD				
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> <u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u>				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
$\overline{\mathcal{O}}$				
SIGNATURE / See / See	TITLE Co	NSTRUCT: ON	Ref DATE 8-	27-13
TYPE OR PRINT NAME	BECK E-MAIL:	WBDS@Che	WIDD COM PHONE: 57.	5-390-1412
For State Use Only		<u></u>	G	1 1
APPROVED BY: Machh	it the TITLE (	onephilice (	Hice DATE OF	3/28/2013

Im

AUG 29 2013