HOB3S OCD

Submit One Copy To Appropriate District 2013 State of New Mexico	Form C-103
Energy Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM-88240-11/50	WELL API NO.
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-05348
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE STATE FEE
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Lovington Paddock Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	0 1/1 1/1 0
1. Type of Well: Oil Well Gas Well Other: Water Injection	8. Well Number 8
2. Name of Operator Chevron Midcontinent, L.P.	9. OGRID Number / 241333
3. Address of Operator	10. Pool name or Wildcat
15 Smith Road Midland, TX 79705	Loyington Paddock
4. Well Location	
Unit Letter: M: 660 feet from the South line and 660 feet from the West line	
Section: 30 Township: 16-S Range: 37-E NMPM County: Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☑ REMEDIAL WORK, ☐ ALTERING CASING ☐	
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRILLING OPNS. 🔲 P AND A	
PULL OR ALTER CASING	
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
$\mathcal{O} \cdot \mathcal{O}$	
SIGNATURE / Les / Yes TITLE Chouron Con	94. Rep DATE 8-4-13
TYPE OR PRINT NAME B: 11 BECK E-MAIL: WADS @ Cherrow. Com PHONE: 575-390-1412	
For State Use Only	
APPROVED BY: Waley Shown File Compliance of words	
SEP 0 3 2013	