HOBBS OCD

Form 3160-4 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

APR 2 3 2013

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

| | WELL (| COMPL | ETION O | RREC | COMPI | ETIO | N REPO | RT | AND L | OG?EC | EIVED | | ease Serial IMNM968 | | | | |
|--|----------------------------|-----------------|--------------------|-------------------|--------------|-----------------|---------------------|-----------------------------------|-----------------------------------|----------------|---|--------------------------------------|------------------------|-------------|--------------|---------------|--|
| la. Type of Well ☑ Oil Well ☐ Gas Well ☐ Dry ☐ Other | | | | | | | | | | | | 6. If Indian, Allottee or Tribe Name | | | | | |
| b. Type of Completion New Well Work Over Deepen Plug Back Diff. Resvr. Other | | | | | | | | | | | 7. Unit or CA Agreement Name and No. | | | | | | |
| Name of Operator Contact: DENISE PINKERTON CHEVRON USA INCORPORATED E-Mail: leakejd@chevron.com | | | | | | | | | | | 8. Lease Name and Well No. CROSS BONES 2-29 1H | | | | | | |
| 3. Address 15 SMITH ROAD 3a. Phone No. (include area code) | | | | | | | | | | | 9. API Well No. | | | | | | |
| MIDLAND, TX 79705 Ph: 432-687-7375 4. Location of Well (Report location clearly and in accordance with Federal requirements)* | | | | | | | | | | | 30-025-40706-00-S1 10. Field and Pool, or Exploratory | | | | | | |
| ALOUS SIMPLALEGIES GENERAL MARKET | | | | | | | | | | | LUSK 11. Sec., T., R., M., or Block and Survey | | | | | | |
| At top prod interval reported below SWSW 560FSL 660FWL | | | | | | | | | | | 0 | r Area Se | , M., OI | 18S R32E | Mer NMP | | |
| At total depth SESE 368FSL 442FEC 4838/m2 Lait? | | | | | | | | | | | | County or 1 .EA | Parish | 13. Sta | | | |
| 14. Date Spudded | | | | | | | | | | | 17. Elevations (DF, KB, RT, GL)* 3693 GL | | | | | | |
| 18. Total Depth: MD 13266 19. Plug Back T.D.: MD 9314 20. Depth TVD | | | | | | | | | | | epth Bridge Plug Set: MD TVD | | | | | | |
| 21. Type Electric & Other Mechanical Logs Run (Submit copy of each) 22. Was well corec | | | | | | | | | | | ed? No Yes (Submit analysis) ? No Yes (Submit analysis) urvey? No Yes (Submit analysis) Yes (Submit analysis) | | | | | | |
| 23. Casing ar | nd Liner Reco | ord (Repo | rt all strings | set in we | · <i>II)</i> | | | | | 2 | | | | | 0 (040 | | |
| Hole Size | Hole Size Size/Grade | | Wt. (#/ft.) | Top (MD | | ottom MD) | Stage Ceme Depth | nter | er No. of Sks. & Type of Cemer | | | Slurry Vol. (BBL) | | Cement Top* | | Amount Pulled | |
| 17.500 | 0 13.375 H-40 | | 48.0 | | | 1140 | | | | 122 | | | | 0 | 0 | | |
| 12.250 | | 25 K-55 | 40.0 | | 0 | 3040 | | | 108 | | 5 | | | 0 | | | |
| 8.750 | 5.500 F | ICP-110 | 17.0 | | 0 | 13254 | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | |
| 24. Tubing | Record | | | | | | | | | - 0 | | | | | <u> </u> | | |
| | Depth Set (N | 4D) P | acker Depth | (MD) | Size | Deptl | n Set (MD) | P | acker De | oth (MD) | Size | Depth Set (MD) Packer Depth (MD) | | | | pth (MD) | |
| 2.875 | | 8727 | | l | | | D 6 | | | | | L | - | | - | | |
| 25. Produci | ormation | | Тор | <u> </u> | Bottom | 26. | Perforation I | | | Т | Size | T : | No. Holes | 1 | Perf. Sta | tue | |
| | SPRING-NO | ORTH | ТОР | 100 1 | | | 1 011012 | Perforated Interval 9655 TO 13 | | | | | | | ODUCING | | |
| В) | | | | | | _ | | | | | | \perp | | <u> </u> | | | |
| <u>C)</u> D) | | | | -+ | | + | | | .= | | | + | | - | | | |
| | racture, Treat | ment, Cer | nent Squeeze | , Etc. | | | | | | L | | | | 1 | | | |
| | Depth Interva | | | | | | 0.5 | Ar | nount and | Type of | Material | | | | | | |
| | 965 | 55 TO 13 | 151 ACIDIZE | - VV/46,60 | 00 GALS | 7 1/2% P | CID | | | <u> </u> | | R | 9:10 L/ | AWI | ATIÛ | Īvi | |
| | | | | | | | | | | | | 17 5-27-13 | | | | | |
| 28 Producti | ion - Interval | Δ | | | | | | | | | | | | | | | |
| Date First | Test | Hours | Test | Oil | Gas | | | Oil Gr | | Gas | | Product | ion Method | | | | |
| Produced 01/15/2013 | Date 04/01/2013 | Tested 24 | Production | BBL 386.0 | MCF 16 | 5.0 | 165.0 | Corr. A | API | Gravi | ty | | ELECTRIC | PUMP | SUB-SURF | ACE, 7 | |
| Choke Size | Tbg. Press. Flwg. SI | Csg. Press. | 24 Hr. Rate | Oil BBL 386 | Gas MCF | | | Gas:Oi Ratio | il 427 | Well | Status | | TEDI | -Ur | KEU | UKU | |
| 28a. Produc | tion - Interva | ıl B | 1 - | | | | 100 | | - 14 | | 1000 | 1 | | | | | |
| Date First Produced | Test Date | Hours Tested | Test Production | Oil BBL | Gas MCF | | | Oil Gr Corr. A | | Gas Grav | | Product | APR | 2] | 2013 | | |
| Choke Size | Tbg. Press. Flwg. | Csg. Press. | 24 Hr. Rate | Oil BBL | Gas MCF | | | Gas:Oi Ratio | ii | Well | Status | | Jan | مد | | | |
| (See Instructi | ions and spa | eas for ad | ditional data | on ravar | sa sidal | | | | | | 1 7 | <u> </u> | | | ANAGEM | | |
| ELECTRON | NIC SUBMI: | SSÍON #2 | 204587 VER | IFIED B | Y THE I | BLM W D ** E | ELL INFOI | RMA ISE | TION S | YSTEM LM RF | VISED2 | BI | tuaahU M-REV± | | J UrriuĒ | | |

| 201- 12 | Lucion Inc. | ol C | | | | | | | | | | |
|--|--|-----------------------|-------------------------------------|--------------------------------------|---------------------------|--|--|--|-------------------------------|---------------------|--------------------|-------------|
| 28b. Proc | luction - Interv | Hours | Test | Oil | Gas | Water | Oil Gravity | Gas | | Production Method | | |
| Produced | Date | Tested | Production | BBL | MCF | BBL | Corr. API | Grav | ity | | | |
| Choke Size | Tbg. Press. Flwg. SI | Csg. Press. | 24 Hr. Rate | Oil BBL | Gas MCF | Water BBL | Gas:Oil Ratio | Weil | Status | | | |
| 28c. Proc | luction - Interv | al D | | | _ | | | | | | | |
| Date First Produced | Test Date | Hours Tested | Test Production | Oil BBL | Gas MCF | Water BBL | Oil Gravity Corr. API | Gas Grav | rity | Production Method | | |
| Choke Size | Tbg. Press. Flwg. SI | Csg. Press. | . 24 Hr. Rate | Oil BBL | Gas MCF | Water BBL | Gas:Oil Ratio | Well | Status | | | |
| | osition of Gas(| Sold, use | d for fuel, ven | ted, etc.) | - | | t | | | <u> </u> | | |
| | nary of Porous | Zones (I | nclude Aquife | ers): | | | | | 31. Fc | ormation (Log) Mar | kers | |
| tests, | all important including depter decoveries. | zones of h interva | porosity and c I tested, cushi | ontents there on used, time | eof: Cored e tool oper | intervals ar n, flowing a | nd all drill-stem nd shút-in pressure | es | | | | |
| | Formation | | Тор | Bottom | | Descrip | tions, Contents, etc |). | | Name | | op Depth |
| BRUSHY CANYON RUSTLER SALADO TANSILL CHERRY CANYON | | | 526 1068 1160 2515 4853 | 6792 1160 2515 4853 5256 | D S | S/LS OLO,SS,S/ ALT, POLY OLO S | | | | | | |
| ADD T/2N | tional remarks ITIONAL TOI ID BONE SPI D BONE SPI | PS RING SA | ND 91 | 19 9483 | | | | | | | | |
| | | | | | _ | | | | | | | |
| 1. El | e enclosed atta ectrical/Mecha andry Notice fo | nical Log | | • / | | ic Report nalysis | | 3. DST Report 4. Directional Survey 7 Other: | | | | |
| | eby certify that | (| Elect Committed to | ronic Subm For CH AFMSS fo | ission #20 EVRON | 4587 Verifi USA INCO | ed by the BLM W RPORATED, sei NNY DICKERSO | Vell Inform nt to the F ON on 04/1 | mation S łobbs 7/2013 (| • | hed instructions): | |
| | | | | | | | | | | 2011 1210 1 | | |
| Signa | iture | (Electro | nic Submiss | ion) | | | Date <u>0</u> | 4/17/201 | 3 | · <u></u> | | - |
| T: 10 : | 1000-1 | 1001 | I Tial. 42 II C | C C | 212 | | | | 1 1110 1 | | | |
| of the Ur | J.S.C. Section ited States any | false fic | r riue 43 U.S. ctitious or frac | C. Section 1 ulent statem | ∠ı∠, make ents or rer | resentations | or any person knov s as to any matter v | wingiy and within its i | ı WIIITULLY Urisdictio | y to make to any de | partment or agency | |