| Submit One Copy To Appropriate District State of New Mexic | co Form C-103 |
|---|--|
| | / |
| LOS N. Carriet De Hakka MA 1996 | WELL APENO |
| 811 S. PHSUSE, ARCSIA, INVI 88210-0 | IVISION 30-25-25157 5. Indicate Type of Lease |
| 1000 Rio Brazos Rd., Aztec, NM 87410 | STATE FEE XX |
| District IV 1220 S. St. Francis Dr., Santa Fe, NM RECENED 87505 | 6. State Oil & Gas Lease No. |
| | · |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR S | |
| PROPOSALS.) 1. Type of Well: Oil Well x Gas Well Other | 8. Well Number 402 |
| 2. Name of Operator 15 A Table. Chevron Midcontinent Library | 9. OGRID Number 4323 |
| 3. Address of Operator | 10. Pool name or Wildcat |
| 15 Smith Road Midland TX 79705 | Drinkard |
| 4. Well Location Unit Letter N: 550 feet from the line and feet from the line | |
| Section 33 Township 21S Range 37E NMPM County Lea | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,452 | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | |
| _ | REMEDIAL WORK ALTERING CASING TO |
| | COMMENCE DRILLING OPNS. □ P AND A X⊠ CASING/CEMENT JOB □ |
| | |
| OTHER: | |
| Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. | |
| A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the | |
| OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR | |
| UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. | |
| FERMANENTLY STAMFED ON THE MARKER SSURFACE. | |
| The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and | |
| other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. | |
| If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with | |
| OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. | |
| All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have | |
| to be removed.) All other environmental concerns have been addressed as per OCD rules. | |
| Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- | |
| retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well | |
| If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. | |
| When all work has been completed, return this form to the appropriate District office to schedule an inspection. | |
| | |
| | struction Rep. (EMC) DATE 9-26-13 |
| TYPE OR PRINT NAME 3:11 /SECK E-MAIL: WBDS@Chevron. Com PHONE: 575-390-1412/ For State Use Only | |
| APPROVED BY: Wall Without TITLE Compliance Officer DATE 10/1/2018 Jun | |
| OCT 0 2 2013 MW | |