Submit One Copy To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Revised November 3, 2011 WELL API NO.
	30-025-25336
District III 811 S. First St., Artesia, NM 88210 District III 2 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE     FEE       6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Central Drinkard Unit
1. Type of Well: Oil Well Gas Well Other:	8. Well Number: 407
2. Name of Operator Chevron USA, Inc.	9. OGRID Number 4323
3. Address of Operator	10. Pool name or Wildcat
15 Smith Road Midland, TX 79705	Drinkard
4. Well Location	
Unit Letter J : 1475 feet from the South line and 1440 feet from the East line	
Section: 33 Township: 21-S Range: 37-E NMPM: County: Lea	
3437' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔀 🛛 REMEDIAL W	ORK 🛛 ALTERING CASING 🗌 <sup>I</sup>
PULL OR ALTER CASING  MULTIPLE COMPL CASING/CEM	
OTHER:  D Location is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
ODED ATOD MAME, A PACE MAME, WELL NUMBED, ADI NUMBED, OLIADTED/OLIADTED I OCATION OD	
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
	sonedule un inspection.
SIGNATURE / Just TITLE: Chevron Construction Rep DATE 9-26-13	
TYPE OR PRINT NAME: Bill Beck       E-MAIL: WBDS@chevror         For State Use Only       Image: Constant State Use Only	n.com PHONE: <u>575-390-1412</u>
TYPE OR PRINT NAME: Bill Beck       E-MAIL: WBDS@chevron.com       PHONE: 575-390-1412         For State Use Only       Mall Here       TITLE       Compliance Officer       DATE       10/1/13         APPROVED BY:       Mall Here       TITLE       Compliance Officer       DATE       10/1/13         Conditions of Approval (if any):       OCT 0 2 2013       Jan	
Conditions of Approval (if any):	OCT 0 2 2013 5 dm
	MW V V
	k. ( .