Office Longitude Minarals of	ew Mexico nd Natural Resources	Form C-103 Revised November 3, 2011
		WELL API NO.
District III Di		30-025-31459 5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410		STATE S FEE
1000 Rio Brazos Rd., Aziec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505		6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name West Lovington Unit
I. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other: Water Injection		8. Well Number: 94
2. Name of Operator Chevron Midcontinent, L.P		9. OGRID Number 241333
3. Address of Operator 15 Smith Bond Midland TV 70705		10. Pool name or Wildcat Lovington, Upper San Andres West
15 Smith Road Midland, TX 79705 4. Well Location		Lovington, Opper San Andres West
Unit Letter E: 2625 feet from the North line and 15 feet from the West line		
Section: 8 Township: 17-S Range: 36-E NMPM: County: Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3894' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL	SUB REMEDIAL WOR COMMENCE DRI CASING/CEMEN	ILLING OPNS. P AND A
FOLL ON ALTER CASING MOLTIFLE COMPL CASING/CLIMENT 30B		
OTHER:		
 ☐ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. ☐ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. ☐ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURETI	TLE_Chevron Construction	n RepDATE
TYPE OR PRINT NAME: Bill Beck For State Use Only	-MAIL: WBDS@chevron.	.com PHONE: <u>575-390-1412</u>
APPROVED BY: Majurable TI Conditions of Approval (if any).	TLE Compliance	Decen DATE 10/1/2013
Conditions of Approval (if any).		OCT 0 2 2013 / don
		Meg