Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office District I HOBBS OCD Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	Revised November 3, 2011 WELL API NO.
District II 811 S. First St., Artesia, NM ₈ 8230 2 6 2013 OIL CONSERVATION DIVISION	30-25-31553 5. Indicate Type of Lease
1000 Pio Proving Pd. Arten NM 97410	STATE xX FEE
District IV 1220 S. St. Francis Dr., Santa FermelVED 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Lovington Sa n Andres Unit
PROPOSALS.) I. Type of Well: Gas Well Other	8. Well Number 87
2. Name of Operator Clevon	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat Loyington, GrayburgSan Anders
4. Well Location	
Unit Letter C : 2,515 feet from the FNL line and 1,462 feet from the FWL line	/ /
Section 01 Township 17S Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON X TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A X PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER:	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
x The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. x Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. x All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not	
have to be removed.) $x \square$ All other environmental concerns have been addressed as per OCD rules.	`
x Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	i files have been removed from lease and wen
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE SIGNATURE TITLE Construction Rep (EMC) DATE 9-26-13
Bill Beck wbds@chevron.com	575- 390 -1412
TYPE OR PRINT NAME E-MAIL:	PHONE:
APPROVED BY: Y LANGUSTOWN TITLE COMPLIANCE	Delecer DATE/0/1/2013/1
U OCT 0 2 20 13 1 ANGS	