District I 1625 N. French Dr., Hobbs, NM 88240 Phone. (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

OCT 2 5 2013

6-3-13

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RECEIVED

				BRADEN	HEAD TES	T REPOR	[
Merit ENErdy						* API Number 300752-85140000			
Ste	te	A-1	f/2 1	Property Name				119	/ell No.
				^{7.} St	urface Locatio	0	-		
VIL - Loi	Section	Township 23 S	Range 36 E		Feet from 1295	N/S Line S	Feet From	E/W Line	County
				,	Well Status				
Well Status		· SHUT-IN		PRODUCING		DATE			

No OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:

Ves

	(A)Surf Casing	(B)Interm Casing(1)	(C)Interm Casing(2)	(D)Prod Csng	(E)Tubing
Pressure	0				SHOF
Flow Characteristics					
คยที	10	Y/N	¥/N	07 N	
Steady Flow	V O	Y/N	Y/N	YIO	
Surges	YO	Y/ N	Y/N	Y7®	
Down to nothing	O'N	Y/N	Y/N	<u>O</u> IN	
Cas or Oil	YO	Y/N	YIN	Y/Q	
Water	Y7N	Y / N	¥7 N	V/N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	RESH	SALTY	SULFUR	BLACK
	······································			

Remarks: Casing had a puft, Surface was Ne	stral before test.	
Pressured casing up to 560psi, tested w	:th chart recorder for	ļ
35 min. Ending pressure was 540psi.		
		:
	EG/0CD 10-28-20	/~
Signature:	OIL CONSERVATION DIVISION	23
Printed name: CHAUS FIORES	Entered into RBDMS	
Title: FORE MAN	Re-test	
E-mail Address HAIS FIGHES C. MERLY ENERLY, COM		
Date: 6-3-13 Phone: 575 420 550C		Į
Witness: N/A		

p.4