Submit 2 Copies To Appropriate District  State of New Mexico	Form C-103
Office District I  State of New Mexico State of New Mexico Energy, Minerals and Natural Resources	October 25, 2007
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210  District III 1301 W. Grand Ave., Artesia, NM 88210  District III  1220 South St. Francis Dr.	30-025-00104 /
1220 South St. Francis Dr.	5. Indicate Type of Lease STATE ☑ FEE ☐
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State ECC
PROPOSALS.)  1. Type of Well:  Gas Well  Other	8. Well Number 1
2. Name of Operator	9. OGRID Number
PALADIN ENERGY CORP / J	164070
3. Address of Operator	10. Pool name or Wildcat
10290 Monroe Drive, Suite 301, Dallas, TX 75229	Caprock: Wolfcamp, East
4. Well Location	
Unit Letter <u>G</u> : <u>1980</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line	
Section 11 Township 12S Range 32E NMPM County Lea	12.50
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON	<del></del>
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT	
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
	concrete. It snows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	ARTER/QUARTER LOCATION OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	ARTER/QUARTER LOCATION OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	ARTER/QUARTER LOCATION OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.	DARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground contour and has other production.	DARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s)	DARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground contour and has other production.	DARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed.	DARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been remoted be removed.)	DARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below grour off this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodiffice the location.  All metal bolts and other materials have been removed. Portable bases have been remoted be removed.)  All other environmental concerns have been addressed as per OCD rules.	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been remoted be removed.)  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b)	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below grour off this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodiffice the location.  All metal bolts and other materials have been removed. Portable bases have been remoted be removed.)  All other environmental concerns have been addressed as per OCD rules.	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been remoted be removed.)  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b)	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been remoted be removed.)  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have NMAC. All fluids have been removed from edule an inspection. If more than one
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been remoted be removed.)  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to scheme.	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have NMAC. All fluids have been removed from edule an inspection. If more than one henalty may be assessed.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodifform lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed be removed.)  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to scheinspection has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be presented to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be presented to a possible to original ground contour and has to be presented to a possibl	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have  NMAC. All fluids have been removed from edule an inspection. If more than one henalty may be assessed.  DATE09/08/13
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grou If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to schinspection has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has other productions.	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have NMAC. All fluids have been removed from edule an inspection. If more than one tenalty may be assessed.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodifform lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed be removed.)  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to scheinspection has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be presented to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be presented to a possible to original ground contour and has to be presented to a possibl	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have  NMAC. All fluids have been removed from edule an inspection. If more than one henalty may be assessed.  DATE09/08/13
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grou If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to schinspection has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has to be made to a P&A location because it does not meet the criteria above, a possible to original ground contour and has other productions.	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have  NMAC. All fluids have been removed from edule an inspection. If more than one henalty may be assessed.  The DATE09/08/13
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below grounly fit his is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodifform lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed be removed.)  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to schinspection has to be made to a P&A location because it does not meet the criteria above, a per SIGNATURE All of the parameter of the param	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed ved. (Poured onsite concrete bases do not have  NMAC. All fluids have been removed from edule an inspection. If more than one henalty may be assessed.  DATE09/08/13