	New Mexico	Form C-103 Revised November 3, 2011
District 1 1625 N. French Dr., Hobbs, NM 88240 HOBBS OCDiergy, Minerals and Natural Resources		WELL API NO.
District II 811 S. First St., Artesia, NM 8821 AUG 21 2000 L CONSERVATION DIVISION		30-025-10041 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NMRECEIVED 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name E. A. Sticher
I. Type of Well: Oil Well Gas Well Other:		8. Well Number: 4
2. Name of Operator Chevron USA, Inc.		9. OGRID Number 4333
3. Address of Operator15 Smith Road Midland, TX 79705		10. Pool name or Wildcat Eunice Southwest, San Andres
4. Well Location		
Unit Letter L: 2310 feet from the South line and 810 feet from the West line		
Section: 4 Township: 22-S Range 37-E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3456' DF		
12. Check Appropriate Box to Indicate Nature of N	otice, Report or Other D	Pata
NOTICE OF INTENTION TO:	,	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON Ø REMEDIAL WORK TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRIL		_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER:		
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the		
A steel marker at least 4 in diameter and at least 4 above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.) All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease; all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE Bill Buck 1	TILE EMC COUSTA	uction REP. DATE. 8-21-13
TYPE OR PRINT NAME 3:11 BECK E	E-MAIL: WBDS@CH	euron. Com.PHONE: 575-390-1412
APPROVED BY: Mal Whiteham 1	TILE Compliance	Officer DATE 08-21-2013
Conditions of Approval (if any):		

DEC 0 4 2013'