Submit One Copy To Appropriate District Stat	e of New Mexico	HORR	socd	Form C-103	
Office District 1 Energy, Mine	erals and Natural Resou	urces		Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II		NOV V	WELL API NO 7 2013 3	0-025-34536	
811 S. First St., Artesia, NM 88210 OIL CONS	ERVATION DIVISI		5. Indicate Typ		
1000 Rio Brazos Rd Azter NM 87410	outh St. Francis Dr.	_	STATE	□ FEE ⊠-	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	ta Fe, NM 87505	KECE	VES tate Qil & (Gas Lease No.	
SUNDRY NOTICES AND REPORT	S ON WELLS		7. Lease Name	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		PARACHUT	TE ADAMS		
1. Type of Well: Oil Well Gas Well Other			8. Well Number 1		
2. Name of Operator			9. OGRID Number		
LEGACY RESERVES OPERATING LP 3. Address of Operator			240974 10. Pool name or Wildcat		
PO BOX 10848, MIDLAND, TX 79702				ORROW, NORTH (GAS)	
4. Well Location			<u></u>		
	SOUTH line and	777	feet from the EA	AST_line	
Section <u>3</u> Township <u>16S</u> Range <u>35E</u>		inty <u>LEA</u>	A		
	w whether DR, RKB, RT 3996' GR				
12. Check Appropriate Box to Indicate Nature	of Notice, Report or	Other Da	ata		
NOTICE OF INTENTION TO:		SUBS	SEQUENT R	EPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS				P AND A	
PULL OR ALTER CASING MULTIPLE COMF		B/CEMENT	JOB U		
OTHER:				pection after P&A	
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 					
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 					
OPERATOR NAME, LEASE NAME, WELL UNIT LETTER SECTION TOWNSHIP A					
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
The location has been leveled as nearly as possible	a aniainal anavud santau	u aud haa h	and alarmad af al	il ingle track flow lines and	
The location has been leveled as nearly as possible to other production equipment.	o original ground contou	ir and has b	een cleared of a	ii junk, trash, flow lines and	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.					
If this is a one-well lease or last remaining well on l					
OCD rules and the terms of the Operator's pit permit and from lease and well location.	r ciosure pian. An now i	mes, produ	iction equipment	and junk have been removed	
All metal bolts and other materials have been remove	ed. Portable bases have b	been remov	ved. (Poured onsi	te concrete bases do not have	
to be removed.)					
 All other environmental concerns have been address Pipelines and flow lines have been abandoned in according to the second second		0 NMAC	All fluids have l	peen removed from non-	
retrieved flow lines and pipelines.					
If this is a one-well lease or last remaining well on l	ease: all electrical service	e poles and	lines have been	removed from lease and well	
location, except for utility's distribution infrastructure.					
When all work has been completed, return this form to the	e appropriate District off	fice to sche	dule an inspectio	on.	
v. C					
SIGNATURE Norm Dracey	TITLE_OPERATIC	<u>DNS SUPEI</u>	RINTENDENT	_DATE _ <u>11/26/2013</u>	
TYPE OR PRINT NAME <u>KEVIN BRACEY</u>	E-MAIL:		P	HONE: <u>432-689-5200</u>	
For State Use Only Malu JHR.	Δ				
APPROVED BY:	2 / 0.00			11/2017012	

A 2013	
---------------	--

DEC 0

Å