Submit 3 Copies To Appropriate District	01-15	Na Massica			Form C-103	
Office District I	State of New Mexico Energy, Minerals and Natural Resources			October 25, 2005		
1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD			30-025-03380			
DIL CONSERVATION DIVISION						
1301 W. Grand Ave., Artesia, NM 88210 Disrtict III OCT 3 1 2012			5. Indicate Type of Lease			
1000 Rio Brazos Rd. Aztec, NM 87410 1220 South St. Francis Dr.			STATE FEE			
District IV Santa Fe, NM 87505			6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM RECEIVED			EO-0392			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO			State WE "B"			
A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				8. Well Number		
1. Type of Well: Oil Well Gas Well Other					3	
2. Name of Operator 9. OGRID Numb						
Apache Corporation				008	373	
3. Address of Operator				ame	7.5 (01) (01)	
303 Veterans Airpark 4. Well Location	Lane, Ste. 3000, Midland	, TX, 79705	<u> </u>	mont; Yates/	7 Rvrs/QN (Oil)	
Unit Letter C	: 1980 feet from th	e N line and	1980	feet from the	W line	
Section 1	Township 21S	Range 35E	NMPM		County Lea	
	11. Elevation (Show whether			F		
	2	3565' GR				
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data						
<u> </u>	INTENTION TO:	I IDEMEDIAL MODE	SUBSE	QUENT REP		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON L CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING O		ALTERING C. P AND A	ASING [7]	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB						
DOWNHOLE COMMINGLE		orionitorozimziti tob				
OTHER: Location is ready for OCD inspection after P&A						
OTHER: Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.						
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.						
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the						
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR						
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR						
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.						
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and						
other production equipment.						
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.						
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with						
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from the lease and well location.						
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have						
to be removed.)						
✓ All other environmental concrens have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from						
non-retrieved flow lines and pipelines.		(),(-)				
When all work has been completed, reinspection has to be made to a P&A leading to the made to the m						
	ocation because it does not mee.	the chiena above, a penalty i	nay be asses	seu.		
SIGNATURE	TITLE	P&A Technic	ian	DATE	10/30/12	
						
, –	on Sellers E-MAIL	leon.sellers@apach	ecorp.com	_PHONE:	432-208-0349	
For State Use Only						
APPROVED BY: Wash Whatalan_TITLE Compliance Off				_DATE	12-4-2013	
Conditions of Approval (if any):						
					<	