Submit One Copy To Appropriate District State of New Mexico Office State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	Revised November 3, 2011
District 1	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 2 5 2013 OIL CONSERVATION DIVISION	30-025-38478
District III	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Off & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Cone 7 Fee
1. Type of Well: Oil Well Gas Well Other	8. Well Number 1
2. Name of Operator	9. OGRID Number
Manzano, LLC 🗸	231429
3. Address of Operator	10. Pool name or Wildcat
PO Box 2107 Roswell, NM 88202-2107	Garrett: Drinkard East
4. Well Location / Unit Letter M: 330 feet from the SOUTH line and 330 feet from the WEST line	
Section 30 Township 16S Range 39E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc., 3690' RKB	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
The second secon	
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod	
from lease and well location.	
All metal bolts and other materials have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Gy Title Operations Forman_	DATE11/21/13
TYPE OR PRINT NAME _Craig Hanagan E-MAIL: _craig@manzanoenergy.com PHONE: 575-623-1996,	
For State Use Only	
APPROVED BY: MILLE COMPLIANCE SILVE DATE 4/2013	
▼	