Submit One Copy To Appropriate District Office	State of Nev		Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240		Revised November 3, 2011 WELL API NO.	
District II 811 S. First St., Artesia, NM 88210	OIL CONSERVAT		30 - 625 - 66980 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Santa Fe, N		STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa i 0, i v	111 07505	6. State Off & Gas Lease No.
	ES AND REPORTS ON W		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	- ·		CENTRAL Drink AND UNIT
1. Type of Well: I Oil Well	as Well 🖸 Other		8. Well Number # 142
2. Name of Operator ChevRon MiDco	NTIMENT L.	p	9. OGRID Number 4 3 2 3
3. Address of Operator			10. Pool name or Wildcat DRINKARD
15 Smith Road	MidlAND T	× 79705	DRINKARD
Unit Letter F : 1,980	• feet from the line a	1, 980 and <u>fee</u> t fro m the	W line
Section 33 Township	p 21 S Range <u>37 E</u> N	IMPM County	
	11. Elevation (Show whether 34.6 4	er DR, RKB, RT, GR, etc	c.) a statistica de la seconda de
12. Check Appropriate Box to I		ce, Report or Other	Data
NOTICE OF INT	ENTION TO	SU	BSEQUENT REPORT OF:
	PLUG AND ABANDON	REMEDIAL WO	RK 🔲 ALTERING CASING 🛄
	CHANGE PLANS	COMMENCE DF	
		-	
OTHER: All pits have been remediated in c	compliance with OCD rules		ready for OCD inspection after P&A
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 			
	. –		
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.	* *		
All metal bolts and other materials to be removed.)	have been removed. Porta	ble bases have been rem	noved. (Poured onsite concrete bases do not have
All other environmental concerns			
Pipelines and flow lines have beer retrieved flow lines and pipelines.	1 abandoned in accordance	with 19.15.35.10 NMA	C. All fluids have been removed from non-
If this is a one-well lease or last re location, except for utility's distribution			
When all work has been completed, ret	emaining well on lease: all e n infrastructure.	electrical service poles a	and lines have been removed from lease and well
	n infrastructure.		•
	n infrastructure.		•
SIGNATURE Bici	n infrastructure.	riate District office to so	•
TYPE OR PRINT NAME B ;//	n infrastructure. turn this form to the approp Rick TITI	riate District office to so LE <u>EMC-Cousteu</u>	chedule an inspection.
	n infrastructure. turn this form to the approp Rick TITI	riate District office to so LE <u>EMC-Cousteu</u>	tion Rep. DATE <u>12-12-13</u> hevron.comPHONE: 575-390-1412