

Submit One Copy To Appropriate District Office

District I  
1625 N. French Dr., Hobbs, NM 88240

District II  
811 S. First St., Artesia, NM 88210

District III  
1000 Rio Brazos Rd., Aztec, NM 87410

District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised November 3, 2011

HOBBS OCD

NOV 18 2013

RECEIVED

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. 30-025-40400 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 39009
7. Lease Name or Unit Agreement Name WC 35 State
8. Well Number 1
9. OGRID Number 256512
10. Pool name or Wildcat Sanmal; San Andres

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CML Exploration, LLC

3. Address of Operator

P.O. Box 890

Snyder, Texas 79550

4. Well Location

Unit Letter J : 2225 feet from the SOUTH line and 1960 feet from the EAST line

Section 35 Township 17 S Range 33 E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4185' RKB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☒

CASING/CEMENT JOB ☐

OTHER: See attached P&A Procedure ☐

☒ Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- ☒ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Jordan Owens TITLE ENGINEER

DATE 11/14/2013

TYPE OR PRINT NAME JORDAN OWENS

E-MAIL: owensj@cmlexp.com

PHONE: 325-573-0750

For State Use Only

APPROVED BY: Mary Brown TITLE Compliance Officer

DATE 1/8/2014

JAN 14 2014



P.O. Box 890  
Snyder, Texas 79550-0890

Ofc: (325) 573-0750 ■ Fax: (325) 573-0749

**HOBBS OCD**

**JAN 08 2014**

**RECEIVED**

January 8, 2014

New Mexico Oil Conservation  
Attn: Maxey Brown  
1625 N. French St  
Hobbs, New Mexico 88240

RE: WC 35 State No. 1  
API # 30-025-40400  
Letter of Violation - Inspection  
Lea County, NM

The excess gravel and caliche has been removed and leveled on the above referenced well site as requested on your Letter of Violation dated December 6, 2013.

Please schedule this well for re-inspection and notify us of any other violations at your earliest convenience.

If you want to call and discuss any of these issues, contact me at 325-574-6295 or e-mail [vonroedern@cmlexp.com](mailto:vonroedern@cmlexp.com).

Sincerely,

Nolan von Roeder