JAN 1 3 2014

Submit One Copy To Appropriate Distriction Office State of New Mexico	Form C-103
District 1 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	Revised November 3, 2011 WELL API NO.
District II OTL CONCEDIA TION DIVISION	30-025-24365
District III 1220 South St. Francis Dr	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	VACUUM GLAYBURS
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	SAN ANDERS UNIT
1. Type of Well: Oil Well Gas Well DOther FNJeetick	8. Well Number # 47
2. Name of Operator Chevron Micconflating.	9. OGRID Number 4/323
3. Address of Operator	10. Pool name or Wildcat VACUUM
15 Smith ROAD MidlAND TX 79705	Gray Burg SAN ANDERS
4. Well Location	
Unit Letter H: 1330 feet from the N line and feet from the E line Section 2 Township 185 Range 34E NMPM County 16A	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON 🖟 REMEDIAL WORK 🔲 ALTERING CASING 🔲 '	
<u> </u>	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	IT JOB L
OTHER: Location is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	\\
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.) All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
\mathcal{T}	
SIGNATURE 13 1 Seek TITLE Chourou Cons	1+. Rep. DATE 1-13-14
TYPE OR PRINT NAME Bill BECK E-MAIL: WBDS OCheuron. Com PHONE: 575-390-1412	
For State Use Only A J Defense A Defense	
APPROVED BY: 1 ALLE DATE /21/2014	
' ()	
	JAN 2 2 2014 &