## HOBBS OCD

## JAN 1 3 2014

Submit One Copy To Appropriate District Office	State of New Mexico	Form C-103 Revised November 3, 2011
	Whiterals and Natural Resources	WELL API NO.
1625 N, French Dr., Hobbs, NM 88240 District II		30-025-25159
811 S. First St., Artesia, NM 88210 OIL C	CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1	220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOTICES AND RI	EDODITE ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL		7. Lease Ivalie of One rigidement reality
DIFFERENT RESERVOIR. USE "APPLICATION FOR PE	ERMIT" (FORM C-101) FOR SUCH	CENTRAL DLINKARD UNIT
PROPOSALS.)  1. Type of Well: Oil Well Gas Well	7 Öller	8. Well Number # 404
2. Name of Operator	1/CA FIN	9. OGRID Number
Chevron Miscontine	TO HE STATE OF THE	4323
3. Address of Operator	N) XIII	10. Pool name or Wildcat
-	dIAND TX 79705	DrinkaRD
4. Well Location Unit Letter P: 460 feet from the S line and feet from the E line		
Section 32 Township 215 Range 37E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3, 463		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
		•
NOTICE OF INTENTION		SEQUENT REPORT OF:
	ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE F		ILLING OPNS. P AND A
PULL OR ALTER CASING   MULTIPLE	COMPL CASING/CEMEN	I JOR 🗀
OTHER:	☐ ⊠ Location is r	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this for	m to the appropriate District office to scl	nedule an inspection.
	_	·
SIGNATURE 13 / Seak	TITLE Chevron Cons	1+ Rep. DATE 1-13-14
TYPE OR PRINT NAME Bill Buck	E-MAIL: wabsoche	1400. COM PHONE: 575-390-1412
For State Use Only		
APPROVED BY: Wah whitala	_ TITLE Compliance	Attion DATE 11-23-2014
THE CONTRACT OF THE PARTY OF TH		
	•	Officer DATE 01-23-2014
		MULTURE TO THE PARTY OF THE PAR