<b>~45</b>	
Submit One Copy To Appropriates State of New Mexico Office	Form C-103
District 1 Energy, Minerals and Natural Resources	Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 2014	30-025-36557
811 S. First St., Artesia, NM 88210  District III  1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
District IV  1000 Rio Brazos Rd., Aztec, NACCENED  District IV  1220 South St. Francis Dr.  Santa Fe, NM 87505	6. State Oil & Gas Lease No. V-2443
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Lotus ALT State
PROPOSALS.)  1. Type of Well: Oil Well Gas Well X Other P&A	8. Well Number #8
2. Name of Operator	9. OGRID Number
Yates Petroleum Corporation	025575
3. Address of Operator	10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210	Livingston Ridge; Delaware SE
4. Well Location	
Unit Letter L : 1980 feet from the South line and 330 feet from the West line	
Section 32 Township 22S Range 32E NMPM Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K $\square$ , ALTERING CASING $\square$ $^{1}$
TEMPORARILY ABANDON	— : — —
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT	Γ'JOB □
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)	ved. (Poured onsite concrete bases do not have
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE In Caused TITLE Ir. Environmental Coordinator DATE 2/19/14	
TYPE OR PRINT NAME L. ON CANONICO E-MAIL: /envirsion @inde	getaleum com PHONE: 748-1471
For State Use Only	Contraction of the second
APPROVED BY: Wash Little Compliance Officer DATE 03/12/2014	
Conditions of Approval (if any):	DATE

MAR 1 3 2014