Submit One Copy To Appropriate District Office District 1 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico Energy, Minerals and Natural Re	esources Revised November 3, 2011 WELL API NO.
District II 811 S. First St., Artesia, NM 882 MAY 28 20 6 IL CONSERVATION DIV	1SION 30=025-05372 /
District III 1220 South St. Francis I 1200 Rio Brazos Rd., Aztec, NM 87410	5. Indicate Type of Lease STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NMRECEIVED 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAG	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC PROPOSALS.)	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	O OCDID Mumber
Chevron Mid Continent U.S.A.	45 23
3. Address of Operator 15 Smith Road Midland Texas. 79705	10. Pool name or Wildcat Lowington Paddock
4. Well Location	
Unit Letter M: 800 feet from the 5 line and 665 feet from the W line	
Section 31 Township 165 Range 376 NMPM County LPA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	EDIAL WORK ALTERING CASING
	MENCE DRILLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING MULTIPLE COMPL CAS	NG/CEMENT JOB
	ocation is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Vand Trefist TITLE Chevron S	urface Rep DATE 5 - 25 - 14
TYPE OR PRINT NAME David Frederick E-MAIL: djzg@	chevron.com PHONE: 903-707-4067
For State Use Only	1. 00 -/-1
APPROVED BY: Wahloh tah TITLE Compliance Officer DATE 5/29/2014	
•	L Dur
	•

÷