

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Brett F. Woods, Ph.D.  
Deputy Cabinet Secretary

Jami Bailey, Division Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

30-Jun-14

HOBBS OCD

JUL 01 2014

BRAMMER ENGINEERING, INC.  
400 TEXAS STREET SUITE 600  
SHREVEPORT LA 71101

RECEIVED

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

**INSPECTION DETAIL SECTION**

**R R SIMS B No.002**

O-4-23S-37E

30-025-41482-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/26/2014	Routine/Periodic	Mark Whitaker	Yes	No	8/25/2014	iMAW1417757939
Violations						
Surface Damage/Restoration						

Comments on Inspection: DO NOT RELEASE. Oil drum on west side of pad. Cellar has not been filled in. Well sign at entrance to location. Barbed wire fence around location. NEED TO REMOVE AND PROPERLY DISPOSE OF OIL DRUM. REMOVE TRASH FROM AND FILL IN CONDUIT AROUND DRY HOLE MARKER TO GROUND LEVEL. REMOVE WELL SIGN, AND REMOVE T-POSTS. CORNER POSTS. AND BARBED WIRE. 1st notice.

**B F HARRISON B**

**No.029**

E-9-23S-37E

30-025-41552-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/25/2014	Routine/Periodic	Mark Whitaker	Yes	No	8/25/2014	iMAW1417659787
Violations						
Surface Damage/Restoration						

Comments on Inspection: DO NOT RELEASE. Operator has not filled in cellar at dry hole marker. NEED TO REMOVE TRASH FROM CONDUIT AND FILL TO SURFACE. 1st notice.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,


  
COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



HASLER 015H14150977  
\$0.48  
07/01/14  
Mailed From 88240

US POSTAGE

BRAMMER ENGINEERING, INC  
400 TEXAS STREET  
SUITE 600  
SHREVEPORT, LA 71101