Submit 3 Copies To Appropriate District Office	State of N	lew Mexic	co		Form	
District I	Energy, Minerals an	nd Natural	Resources	Carron Control	May 2	27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-025-21746	~	
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVA			5. Indicate Type of	Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South S			STATE 🛛	FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe,	INIVI 8/30	13	6. State Oil & Gas I E-	Lease No. 7574	
SUNDRY NOTION	CES AND REPORTS ON			7. Lease Name or U	nit Agreement l	Name
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM	C-101) FOR S	UCH		ge Morrow Unit	
1. Type of Well: Oil Well	Gas Well Other XX-	Storagobe	SOCD	8. Well Number	03	
2. Name of Operator	/			9. OGRID Number		
Enstor Grama Ridge Storage & Tra 3. Address of Operator	asportation LLC	<u> </u>	7 2014	10. Pool Name or W	234255 Tildcat	
20329 State Highway 249, Suite 40	00 Huston, TX 77070			Grama Ridge Mor		
4. Well Location		REC	EIVED			
Unit LetterJ:_	_1980feet from the _	South	line and	1980fe	et from the	_
Eastline						
Section 33 Township		łЕ		ea County, NM		
and the second of the second o	11. Elevation (Show whe	ther DR, RR GL 3640		-		
Pit or Below-grade Tank Application 🗌 or	Closure	OL 3040			•	
Pit type Depth to Groundwa		est fresh water	well Distanc	e from nearest surface wa	iterN/A	
Pit Liner Thickness: mil	Below-Grade Tank: Volume		bbls; Constru	ction Material		
12. Check A	ppropriate Box to Indi	icate Natu	re of Notice.	Report or Other D	ata	
	• •	1	•	•		
NOTICE OF IN PERFORM REMEDIAL WORK □			SUI REMEDIAL WOR	BSEQUENT REF	PORT OF: ALTERING CAS	CINC [
	PLUG AND ABANDON CHANGE PLANS			RK □ RILLING OPNS.□		
PULL OR ALTER CASING	MULTIPLE COMPL	1	CASING/CEMEN		ANDA	ы
OTHER:		1	OTHER:	11 000		П
13. Describe proposed or compl				l give pertinent dates,	including estima	ated date
of starting any proposed wo	rk). SEE RULE 1103. For					
or recompletion. 1. Cmt sqz open Morrow perfs		92 av Class	. II and disulans	TOC to 12 920' Dans)O ai
 Cmt sqz open Morrow perfs Spot 100 sx Class H from 1 					sure test to 1,00	o ber
3. Set CIBP @ 10,563', place 3	25 sx Class H on top, & pro	essure test to	o 1,000 psi	•		
4. Spot 60 sx Class H cmt from	1 8,000-8,225' inside 7" cs	g & pressur	e test to 1,000 ps	si	00 · WOC	FTAG
 4. Spot 60 sx Class H cmt fron 5. Perforate 7" csg @ 5,806' as ←6. Spot 60 sx Class C cmt plug 	id squeeze with 80 sx Clastinside 7" csg from 2,400-	ss C and disp	place cmt to 5,60	06'. Pressure test to 50	J0 psi. 6000	
7. Perforate 7" csg @ 475' and	circulate 250 sx Class C is	nside 7"x9-	5/8" annulus & 7	" csg, place TOC @ :		to verify.
8. Mechanical cut 7" csg @ 5'	BGL, cut off well head an	d anchors @	3' BGL, install	well marker, and ID	plate.	-
Perf@ 1800'	saz 40 sxs C	LASS	C CMT.	WOC & TA	-ئ 	
		•				
I hereby certify that the information a	bove is true and complete	to the best of	of my knowledge	and belief. I further c	ertify that any pit (or below-
grade tank has been/will be constructed or						
SIGNATURE ()	TITLE	Proc. No	·	DATE	F: 6/30/14	
). <u>0/30/14</u>	
Type or print name: E-mail	address: Telephone No.	281	- 374 - 305			,
For State Use Only	нL	`.) /	1	. ا بد	//
APPROVED BY:	HOWN I	itle Dù	st. Due	revisor i	DATE ///0	12014
Conditions of Approval (if any):					7//	` ` `
V	Blown TI					M
					. Men AA1	A "
				ไปป	L 20 2A1	\$ [*]

Enstor

Field: Grama Ridge Morrow

03

Lease/County: Grama Ridge Morrow Unit/Lea County

Location: J Unit, Section 33, Township 21S, Range 34E

DATE **API #:**

06/09/2014 30-025-21746

DRAWING STATUS

Current

DRAWING BY

M. Morris- CMWS

RKB	16'
Annular Fluid	9.9 ppg brine
Top Xmas Tree Flange	2-9/16" 10M

13-3/8" 48# H40 8rd @ 375' CTOC @ surface, tested to 1,000 psi for 30 min on 03/06/1966

SITP: 2,448 psi SICP: 4,500 psi

TUBING

2-7/8"

6.5#

L80

8rd ABC Mod

2.441"

0-12,839'

OD

PPF

Grd

Thrd

Depth

20% of 7" 29# MIY: 2,244 psi 10% of 7" MIY: 1,122 psi MASP: 5,000 psi

Completion Detail					
 Туре	Depth				
Baker Model DB Pkr	12,839'				

Differential temperature & noise survey on 10/16/2013 indicate packer is Leaking and old squeeze perfs @ 11,760 to 11,914' are leaking

fluid into annulus

Schlumberger pipe analysis log on	
08/26/1982 Indicates moderate inner	_
casing damage @ 10,390-11,410'	
Cmt sqz on liner lap on 08/29/1982	
Pressure tested to 2,100 psi for 30 min	
Csg parted @ 11,378' on 08/18/1982	•

Size	13-3/8"	9-5/8"	7"	4-1/2"
Weight	48"	36#/40#	29#	13.5#
Grade/ Thrd	H40 8rd	J55	N80 8rd	P110 LTC
Hole Size	17-1/2"	12-1/2"	8-3/4"	6"
Depth	357'	5,706'	11,900'	11,593-13,396'
СМТ	432 cuft	1,998 cuft	702 cuft	243 cuft
стос	Surface	Surface	7,229'	TOL

9-5/8" 36#/40# J55 8rd @ 5,706'

For 30 min on 03/19/1966

CTOC @ surface, tested to 2,000 psi

Differential temp & noise survey On 10/16/2013 indicate possible tubing leaks @ 10,835' and 10,870'

one Spring perfs: 10,663-712' cmt Sqz w/ 250 sxs on 07/31/1982

Strawn Sand perfs: 11,760-914'. Cmt sqz w/ 250 sxs on 07/31/1982

7" 29# P110 LTC @ 11,900' CTOC @ 7,229', tested csg to 3,500 psi for 30 min on 06/12/1998

Atoka Sand perfs: 12,851-857' MD Cmt sqz w/ 250 sxs, final test pressure @ 5,800 psi., SBHP: 2,286 psi, BHT-184 on 04/13/2005

Morrow perfs: 13,029-077'

Morrow perfs: 13,173-198' MD Morrow perfs: 13,245-252' MD

4-1/2" 13.5# P110 liner f/ 11,593-13,396' Tested to 5,000 psi for 30 min on 05/30/1966 CTOC @ TOL

TD 13.403' RKB PBTD: 13,350'

Enstor

Field: Grama Ridge (Morrow) WELL 3

Lease/County: Grama Ridge Morrow Unit/Lea County DATE

Location: J Unit: S-33, T-21S, R-34E

API#:

06/14/2014

30-025-21746

DRAWING STATUS

PROPOSED P&A

DRAWING BY

M. Morris- Production Engr

RKB	16'
Annular Fluid	12 ppg WBM
Top Xmas Tree Flange	2-9/16" 10M

13-3/8" 48# H40 8rd @ 375' CTOC @ surface, tested to 1,000 psi for 30 min on 03/06/1966

Mechancial cut 7" 29# csg @ 5' BGL, cut off well Head & anchors 3' BGL Install well marker & ID plate

40

Spot 60 sxs Class C cmt from 2,400-2,600'. Pressure test plug to 500 psi for 30 minutes

PERF @ 1800

Perforate @ 475'. Circulate & place 250 sxs Class C cmt inside 7"x9-5/8" annulus & 7" csg, place TOC to 5' BGL, tag to verify

Perforate @ 5,806' & sqz with 80 sx Class C. Displace cmt to 5,606 Pressure test plug to 500 psi for 30 minutes'

WOC & TAG

Place 60 sx Class H cmt from 8,000 to 8,225', pressure test plug to 1,000 psi for 30 minutes

Set CIBP @ 10,563', circulate 9.0 ppg salt gel & pressure test to 1,000 psi for 30 minutes Place 25 sx Class H on CIBP, estimate TOC @ 10,437'

Place 100 sxs Class H cmt from 11,493' – 12,000' Pressure test 7" csg to 1,000 psi for 30 minutes

Squeeze Morrow with 82 sx Class H, place TOC @ 12,839', pressure test plug to 1,000 psi for 30 minutes

Schlumberger pipe analysis log on 08/26/1982 \ Indicates moderate inner casing damage @ 10,390-11,410

Cmt sqz on liner lap on 08/29/1982, Pressure tested to 2,100 psi for 30 min.

Size	13-3/8"	9-5/8"	7"	4-1/2"
Weight	48"	36#/40#	29#	13.5#
Grade/ Thrd	H40 8rd	J55	N80	P110 LTC
Hole Size	17-1/2"	12-1/2"	8-3/4"	6"
Depth	357'	5,706'	11,900'	11,593-13,396'
СМТ	432 cuft	1,998 cuft	702 cuft	243 cuft
стос	Surface	Surface	7,229'	TOL

For 30 min on 03/19/1966

9-5/8" 36#/40# J55 8rd @ 5,706' CTOC @ surface, tested to 2,000 psi

SITP: 2,448 psi SICP: 2,050 psi

20% of 7" 29# MIY: 2,244 psi 10% of 7" MIY: 1,122 psi MASP: 3,000 psi

Bone Spring perfs: 10,663-712' cmt Sqz w/ 375 sxs

Strawn Sand perfs: 11,760-914', Cmt sqz w/ 250 sxs

7" 29# P110 LTC @ 11,900' CTOC @ 7,229', tested csg to 3,500 psi for 30 min on 06/12/1998

Atoka Sand perfs: 12,851-857' MD Cmt sqz w/ 127 sxs, final test pressure @ 5,800 psi., SBHP: 2,286 psi, BHT-184 on 04/13/2005

Morrow perfs: 13,029-077'
Perfs: 13,143-13,148 cmt saz w/ 42 sx

Morrow perfs: 13,173-198' MD Morrow perfs: 13,245-252' MD

TD 13,403' RKB 4-

PBTD: 13,350'

4-1/2" 13.5# P110 liner f/ 11,593-13,396' Tested to 5,000 psi for 30 min on 05/30/1966

CTOC @ TOL