


State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

Jami Bailey, Division Director
Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

30-Jul-14

CIMAREX ENERGY CO. OF COLORADO

202 S. CHEYENNE AVE, STE 1000

TULSA OK 74103

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

BUNKER HILL 32 STATE COM No.003				I-32-15S-31E	30-005-28024-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/29/2014	Routine/Periodic	Mark Whitaker	Yes	No	11/1/2014	iMAW1421034992
Violations						
Surface Damage/Restoration						
Comments on Inspection:		The permit to drill this well has expired and therefore the authority to drill has been canceled. In anticipation of drilling, a location was built and a cellar was installed. OPERATOR SHOULD REMOVE CELLAR BOARDS AND FILL CELLAR IN. ALSO CONTOUR LOCATION IF ANY PILES OF DIRT OR CALICHE ARE PRESENT.				

NASSAU 29 STATE COM No.001				D-29-15S-31E	30-005-29168-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/29/2014	Routine/Periodic	Mark Whitaker	Yes	No	11/1/2014	iMAW1421039307
Violations						
Surface Damage/Restoration						
Comments on Inspection:		The permit to drill this well has expired and therefore the authority to drill has been canceled. In anticipation of drilling, a location was built and a cellar was installed. OPERATOR SHOULD REMOVE CELLAR BOARDS AND FILL CELLAR IN. ALSO CONTOUR LOCATION IF ANY PILES OF DIRT OR CALICHE ARE PRESENT.				

JUL 30 2014

CITGO SE STATE No.002

A-17-22S-36E

30-025-25546-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/28/2014	Routine/Periodic Violations	Mark Whitaker	Yes	No	10/31/2014	iMAW1420935492
Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Well sign not legible (19.15.16.8). NEED TO REPLACE WELL SIGN.						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,




COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



CIMAREX ENERGY CO. OF COLORADO
202 S. CHEYENNE AVE.
SUITE 1000
TULSA, OK 74103