## State of New Mexico

HOBBS OCD

## **Energy, Minerals and Natural Resources Department**Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT** 

AUG 01 2014

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating									30-025-10634		
Property Name SKELLY PENROSE B UNIT									Well No.		
					<sup>7</sup> Surface Locati	ion					
UL - Lot E	Section 5	Township 23S	Range 37E	-	Feet from 1980	N/S Line NORTH	Feet From	n	E/W Line WEST	County LEA	
<u></u>					Well Status	<u> </u>					
Well Status			SHUT-IN		PRODUCING A - INJ	O7/02/20		í		***	
If bradenhead			HEAD AND INT		IATE TO ATMOSPHI OBSERVED DA pply:		Y FOR 15 N	1INUTES	EACH		
		(A)S	(A)Surf-Interm		rm(1)-Interm(2)	(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure			<u>0#</u>					0#		495#	
Flow Charac	teristics									1	
Puff		_	N		Y/N	Y/N		Y		7	
Steady F			Y/N		Y/N	Y/N		N		]	
Surge			Y/N		Y / N	Y/N		N		]	
Down to no Gas or t	_		Y/N		Y/N Y/N	Y/N		Y/N			
Water			N		- Y / N	Y/N		N		_	
If bradenbead CLEAR	flowed wa		check all of the description		SALTY	SULFUR		BLACK			
Remarks:					FOR R	ECORD (	ONLY 8/8/5				
Printed name: C. DALE KELTON  Title: PRESIDENT  E-mail Address: providenceenergy@suddenlink.net							OIL CONSERVATION DIVISION Entered into RBDMS Re-test				
Date: 07/25	2014		Phone: 432-	661-1364							

Witness:

UG 1 2 2014