

AUG 11 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Kaiser-Francis Oil Company		API Number 30-025-10448
Property Name Danglade		Well No. 001

7. Surface Location

UL - Lot B	Section 24	Township 22S	Range 37E	Feet from 660	N/S Line North	Feet From 1980	E/W Line East	County LEA
---------------	---------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR NO	SWD NO	OIL YES	PRODUCER YES	GAS NO	DATE 07-22-2014
------------------	----------------	-----------	----------------	-----------	------------	-----------------	-----------	--------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure		300#		40#	0#
Flow Characteristics		Bled down in 58 seconds			
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

No Bleed Down on csg or tbg on producing wells.
(Gunning). 8/1/14
8-19-14

BS 8/17/2014

Signature: <i>Teresa Nixon</i>		OIL CONSERVATION DIVISION
Printed name: Teresa Nixon		Entered into RBDMS
Title: Regulatory Compliance Analyst		Re-test
E-mail Address: teresami@kfoc.net		
Date: 08-07-14	Phone: 918-491-4591	
Witness: Bill Sonnamaker, OCD Staff Manager		

AUG 21 2014

h